Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 31 Mar 2023

Preliminary Advice

Vehicle No : SLD1615G Accident Date : 04/02/2023

Make : HONDA VEZEL Policy No. : SPMF1000000542

Date of Inspection : 21/02/2023 Est. Duration of Repair : 10

Inspection At : DING AUTO PTE LTD (HQ)

176 SIN MING DRIVE #04-06, SIN MING AUTOCARE

SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,447.00 (Estimate \$19,404.00 + Supplementary \$1,043.00)
Revised Amount	:S\$	17,443.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,443.50
Lump Sum Repair	:S\$	13,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	21,841.00
Salvage Value	:S\$	

Margin for Repair :S\$ 25,159.00

Remarks

(X	,	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.