

# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd  
79 Robinson Road  
#09-01  
Singapore 068897

### Claim Details

Case Ref. No. : OD/022023/5984  
Date : 13-02-2023  
Accident Date : 13-02-2023

### Vehicle Details

Make & Model : Renault GRAND SCENIC IV 1.5  
DCI AT EU6  
Chassis No : VF1RFA00059238203  
Registration No : SME2476S

S/N	Description	Qty	Amount (S\$)	
1	FRONT BONNET <i>hnc</i>	1.00	\$1,150.00	✓
2	FRONT BONNET RH HINGE <i>bt</i>	1.00	\$110.00	✓
3	FRONT BONNET LH HINGE <i>bt</i>	1.00	\$110.00	✓
4	FRONT BONNET RH RUBBER <i>sv</i>	1.00	\$60.00	X
5	FRONT BONNET LH RUBBER <i>sv</i>	1.00	\$60.00	X
6	FRONT BONNET INSULATOR <i>crumpled</i>	1.00	\$150.00	✓
7	FRONT BONNET LOCK <i>bt</i>	1.00	\$200.00	✓
8	FRONT GRILLE BASE <i>broken</i>	1.00	\$400.00	✓
9	FRONT GRILLE OUTER CHROME GARNISH <i>crack</i>	1.00	\$290.00	✓
10	FRONT GRILLE MOULDING <i>bt</i>	1.00	\$190.00	✓
11	FRONT GRILLE LOWER CHROME MOULDING <i>crack</i>	1.00	\$270.00	✓
12	FRONT GRILLE EMBLEM <i>broken</i>	1.00	\$190.00	✓
13	FRONT RH HEADLAMP <i>broken</i>	1.00	\$770.00	✓
14	FRONT LH HEADLAMP <i>minorly crack</i>	1.00	\$770.00	✓
15	FRONT RH HEADLAMP BRACKET <i>bt</i>	1.00	\$50.00	✓
16	FRONT LH HEADLAMP BRACKET <i>bt</i>	1.00	\$50.00	X
17	FRONT BUMPER <i>tdn</i>	1.00	\$1,450.00	✓
18	FRONT BUMPER LOWER PAD <i>distorted</i>	1.00	\$400.00	✓
19	FRONT BUMPER CENTRE LOWER GRILLE <i>deformed</i>	1.00	\$390.00	✓
20	FRONT BUMPER TOWING COVER <i>cut</i>	1.00	\$30.00	✓
21	FRONT BUMPER RH FOG LAMP <i>dislodged</i>	1.00	\$170.00	✓
22	FRONT BUMPER LH FOG LAMP <i>td</i>	1.00	\$170.00	X
23	FRONT BUMPER RH FOG LAMP COVER <i>dislodged</i>	1.00	\$170.00	✓
24	FRONT BUMPER LH FOG LAMP COVER <i>td</i>	1.00	\$170.00	X
25	FRONT BUMPER RH SIDE RETAINER <i>dislodged</i>	1.00	\$110.00	✓
26	FRONT BUMPER LH SIDE RETAINER <i>td</i>	1.00	\$110.00	X
27	FRONT BUMPER RH INNER PAD <i>broken</i>	1.00	\$90.00	✓
28	FRONT BUMPER LH INNER PAD <i>td</i>	1.00	\$90.00	X
29	FRONT BUMPER SPONGE <i>broken</i>	1.00	\$80.00	✓
30	FRONT BUMPER REINFORCEMENT <i>bt</i>	1.00	\$630.00	✓

# Vin's

Vin's Motor Pte Ltd  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

31	FRONT BUMPER REINFORCEMENT RH BRACKET <i>yt</i>	1.00	\$140.00	✓
32	FRONT BUMPER REINFORCEMENT LH BRACKET ?	1.00	\$140.00	?
33	FRONT BUMPER UNDER COVER ?	1.00	\$450.00	?
34	FRONT BUMPER CLIPS <i>hcc</i>	10.00	\$30.00	✓
35	FRONT SUPPORT PANEL <i>broken</i>	1.00	\$1,050.00	✓
36	FRONT SUPPORT PANEL TOP COVER <i>broken</i>	1.00	\$130.00	✓
37	FRONT SUPPORT PANEL TOP COVER CLIPS <i>hcc</i>	10.00	\$30.00	✓
38	AIRCON CONDENSER <i>yt</i>	1.00	\$880.00	✓
39	AIRCON CONDENSER DISCHARGE PIPE ?	1.00	\$350.00	?
40	AIRCON CONDENSER RECEIVER PIPE ?	1.00	\$280.00	?
41	AIRCON CONDENSER SUCTION PIPE ?	1.00	\$380.00	?
42	RADIATOR <i>yt</i>	1.00	\$690.00	✓
43	RADIATOR TOP HOSE ?	1.00	\$60.00	?
44	RADIATOR LOWER HOSE <i>hh</i>	1.00	\$60.00	X
45	RADIATOR FAN MOTOR ?	1.00	\$870.00	?
46	TURBO COOLER ?	1.00	\$780.00	?
47	TURBO COOLER DUCT <i>broken</i>	1.00	\$150.00	✓
48	AIR CLEANER BOX ?	1.00	\$210.00	?
49	AIR CLEANER BOX HOSE ?	1.00	\$50.00	?
50	ALTERNATOR ?	1.00	\$800.00	?
51	AIRCON COMPRESSOR ?	1.00	\$2,000.00	?
52	FAN BELT ?	1.00	\$60.00	?
53	WIPER TANK <i>hh</i>	1.00	\$160.00	X
54	FRONT RH FENDER <i>broken</i>	1.00	\$550.00	✓
55	FRONT RH FENDER INNER SHIELD ?	1.00	\$310.00	?
56	FRONT RH FENDER INNER SHIELD CLIPS <i>hh</i>	10.00	\$30.00	X
57	FRONT LH FENDER <i>hh</i>	1.00	\$550.00	X
58	DASHBOARD <i>broken</i>	1.00	\$3,100.00	✓
59	DASHBOARD COVER <i>hh</i>	1.00	\$800.00	X
60	STEERING AIRBAG <i>activated</i>	1.00	\$950.00	✓
61	PASSENGER AIRBAG <i>activated</i>	1.00	\$1,000.00	✓
62	STEERING CLOCK SPRING SENSOR <i>activated</i>	1.00	\$600.00	✓
63	AIRBAG SENSOR <i>activated</i>	1.00	\$220.00	✓
64	AIRBAG ECU <i>activated</i>	1.00	\$1,200.00	✓
65	FRONT RH SEAT BELT <i>activated</i>	1.00	\$630.00	✓
66	FRONT LH SEAT BELT <i>activated</i>	1.00	\$630.00	✓
67	REAR RH SEAT BELT <i>activated</i>	1.00	\$730.00	✓
68	REAR LH SEAT BELT <i>activated</i>	1.00	\$730.00	✓
			\$30,660.00	
			Margin: 10%	
			\$3,066.00	
			\$33,726.00	
69	FRONT NO. PLATE <i>cut / scratched</i>	1.00	\$40.00	


# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

70	COOLANT H-H	1.00	\$80.00	44
71	TO REFILL AIRCON GAS	1.00	<del>\$150.00</del>	120/-
72	TO RESET HEADLAMP SYSTEM AND ECU	1.00	<del>\$280.00</del>	130/-
73	TO RESET AIRBAG SYSTEM AND ECU	1.00	\$380.00	350/-
74	TO REMOVE AND REPLACE DASHBOARD	1.00	<del>\$380.00</del>	180/- 250/-
75	TO REPAIR FRONT DAMAGES	1.00	<del>\$980.00</del>	900/-
76	TO SPRAY PAINTING	1.00	<del>\$1,200.00</del>	800/-
<b>Subtotal w/o GST:</b>			<b>\$37,216.00</b>	

21/02/2023 @ 1630h

Mr Andrew  
P/Pant.



LKK studio



Excurs TISA.

- Photo after  
repair with  
damaged parts.

- No spare parts.  
Need to indent.

Issued by Iswan

This is a computer-generated document. No signature is required.