

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER:

ECOS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1727
Policy No:	MPC23P0002100	Date of Loss:	18/02/2023
Vehicle Reg. No.:	SLW310SD	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	QUEK CHIN MING		

Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	06/02/2018
Vehicle Colour:	SILVER		
Engine No:	2ZR0A53483	Chassis No:	JTDGG20W30J008775
Odometer:	73551 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location: WAH HONG MOTORS & CREDIT PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	3,377.00
Miscellaneous Items	145.00
Labour	2,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,082.00
+ GST 8.00% (S\$)	486.56
Nett Amount (S\$)	6,568.56

This claim is handled by: CHAN PEI PEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Wah Hong Motors & Credit Pte Ltd/SLW3103D/20/02/2023 16:16	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>hm</i> ✓	0.00	0.00	*300.00 F
2	1		*Bonnet hinge RH/LH@2*\$40 <i>W</i> ✓	0.00	0.00	*80.00 F
3	1		*Bonnet logo badge <i>W</i> ✓	0.00	0.00	*30.00 F
4	1		*Bonnet lock <i>X</i>	0.00	0.00	*70.00 F
5	1		*Center grille with outer chrome <i>?</i>	0.00	0.00	*140.00 F
6	1		*Front bumper <i>cm</i> ✓	0.00	0.00	*240.00 F
7	1		*Front bumper side retainer RH/LH@2*\$40 <i>X</i>	0.00	0.00	*80.00 F
8	1		*Headlamp RH/LH@2*\$400 <i>cm</i> ✓	0.00	0.00	*800.00 F
9	1		*Support panel <i>repm</i> ✓	0.00	0.00	*580.00 F
10	1		*Brace panel <i>?</i>	0.00	0.00	*70.00 F
11	1		*Condenser <i>?</i>	0.00	0.00	*480.00 F
12	1		*Front reinforcement <i>?</i>	0.00	0.00	*140.00 F
13	1		*Front bumper sponge <i>?</i>	0.00	0.00	*60.00 F
14	1		*Front fender RH/LH (Repair refer to labour)	0.00	0.00	*-F
15	1		*Front door RH/LH (Repair refer to labour)	0.00	0.00	*-F

F=Franchise part.

Sub Total (\$\$)	3,070.00
+ Margin on L,N Items 10.00% (\$\$)	307.00
Total Parts (\$\$)	3,377.00

Wah Hong Motors & Credit Pte Ltd/SLW3103D/20/02/2023 16:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	Center grille clips	20	25.00
2	1	Coolant	30	50.00
3	1	Front bumper clips	30	35.00
4	1	Front car plate with holder		35.00

Sub Total (S\$) 145.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	600	1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1200	1,400.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30	60.00
4	To remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New	? 80	100.00

Gross Labour Cost (S\$) 2,560.00

Wah Hong Motors & Credit Pte Ltd/SLW3103D/20/02/2023 16:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068

7 days

4/8

22/02/23 @ 1400

EXCESS TBA

Revers

Reg after repair