

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/FC/23001921/UWY3

**ASSIGNMENT**

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour

A/C:

Sp. Reading

T/Radio:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$ )

☐

: Interview (\$ )

☐

: Tech. Invs (\$ )

☐

: Weekend (\$ )

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL



# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
CHUA CHIANG YONG BLK 892A TAMPINES AVENUE 8 #07-24 SINGAPORE 521892 Contact No Mobile: 88939269	Cust No/Name KCV19079/CHUA CHIANG YONG Reg No/Reg Date SMZ4974Y*#F / 29/04/202 Date In/Mileage 20/02/2023/ 170204 Chassis No GF7W0701133 Engine No 4J11DA7851 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	20/02/2023/ 13:55	REN	979 / Renemer Ramirez Bag	14726			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 19/02/2023 ALONG TAMPINES AVE 8 LOT#350 OPEN SPACE CARPARK								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT VEHICLE								
TP#: GBK6289M TP INS: MS FIRST CAPITAL								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE								
A 54900099								
TO CHECK WIRING AND ELECTRICAL SYSTEM								
E PNT88000								
TO REPLACE TAILGATE GLASS & MOULDINGS								
E PNT88000								
TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS								
E PNT88000								
TO TRANSFER TAILGATE COMPONENTS & MECHANISM								
E PNT88000								
TO REMOVE & RE-INSTALL FLOOR BOARDS, TRIMS & CARPETS TO FACILITATE								
REPAIR ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								
TO REPLACE EMBLEM, LOGO, TAILGATE PNL, LATCH, W/STRIP, GARNISH, REAR BUMPER,								
EXTENSION, CLIPS, BRACKETS, REFLECTOR LAMP, ANTENNA, BUZZER, ETC								
-TO REPAIR REAR END PANEL								
STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS								
E PNT98000								
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
(TAILGATE PNL, REAR BUMPER, REAR EDN PANEL)								
E PNT88000								
TO CHECK & TEST REVERSE SENSOR								
E PNT88000								
TO SUPPLY ONE SET REVERSE SENSOR								
E PNT88000								
TO SUPPLY REAR LICENSE PLATE WITH FRAME								
M SUNDRY								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



CYCLE &amp; CARRIAGE

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
CHUA CHIANG YONG	Cust No/Name KCV19079/CHUA CHIANG YONG
BLK 892A TAMPINES AVENUE 8	Reg No/Reg Date SMZ4974Y*#F / 29/04/202
#07-24	Date In/Mileage 20/02/2023/ 170204
SINGAPORE 521892	Chassis No GF7W0701133
Contact No Mobile: 88939269	Engine No 4J11DA7851
	Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	20/02/2023/ 13:55	REN	979 / Renemer Ramirez Bag	14726		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS						100	200.00
M SUNDRY							
TO APPLY BODY SEALANT ON NEW PANELS						100	200.00
M SUNDRY							
TO APPLY ANTI-CORROSION ON AFFECTED AREAS						per	50.00
M SUNDRY							
TO SUPPLY MIVEC EMBLEM						per	50.00
M SUNDRY							
TO SUPPLY C&C BADGE						per	20 50.00
M SUNDRY							
SUNDRIES							
M GLASS, TAILGATE WINDOW				1.00	695.00	00.00	695.00
M DAM, TAILGATE, UPR				1.00	13.00	00.00	13.00
M DAM, TAILGATE SIDE				2.00	33.00	00.00	66.00
M DAM, TAILGATE, LWR				1.00	25.00	00.00	25.00
M FASTENER, WINDSHIELD				4.00	8.00	00.00	32.00
M STOPPER, WINDSHIELD GLASS				2.00	4.00	00.00	8.00
M MARK, OUTLANDER				1.00	118.00	00.00	118.00
M MARK, THREE-DIA				1.00	63.00	00.00	63.00
M GARNISH, TAILGATE				1.00	502.00	00.00	502.00
M PANEL ASSY, TAILGATE				1.00	1025.00	00.00	1025.00
M LATCH, TAILGATE				1.00	229.00	00.00	229.00
M W/STRIP, TAILGATE OPENING				1.00	220.00	00.00	220.00
M FACE, RR BUMPER				1.00	857.00	00.00	857.00
M EXTENSION, RR BUMPER				1.00	292.00	00.00	292.00
M CLIP, ENG ROOM COVER				5.00	2.00	00.00	10.00
M CLIP, RR BUMPER				15.00	6.00	00.00	90.00
M CLIP, FR BUMPER				5.00	4.00	00.00	20.00
M LH SIDE BRKT, R/BMPR FACE				1.00	20.00	00.00	20.00
M RH SIDE BRKT, R/BMPR FACE				1.00	20.00	00.00	20.00
M LH REFLECTOR, TAIL LAMP				1.00	103.00	00.00	103.00
M RH REFLECTOR, TAIL LAMP				1.00	103.00	00.00	103.00
M ANT, KEYLESS OPERATION, RR				1.00	99.00	00.00	99.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHUA CHIANG YONG	Cust No/Name	KCV19079/CHUA CHIANG YONG
BLK 892A TAMPINES AVENUE 8	Reg No/Reg Date	SMZ4974Y*#F / 29/04/202
#07-24	Date In/Mileage	20/02/2023/ 170204
SINGAPORE 521892	Chassis No	GF7W0701133
Contact No Mobile: 88939269	Engine No	4J11DA7851
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	20/02/2023/ 13:55	REN	979 / Renemer Ramirez Bag	14726
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BUZZER,KEYLESS OPERATIO,RR	11	1.00	94.00	00.00	94.00
<div style="text-align: center; font-size: 48px; opacity: 0.3;">Estimate</div> <div style="border: 1px solid black; padding: 10px; margin: 10px auto; width: 80%;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>					

Confirm & accepted by

Nett	12,664.00
8% GST on	12664.00
<b>Total Payable</b>	<b>13,677.12</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	667E
Vehicle Details	
Vehicle No.:	SMZ4974Y
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2023
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.0 CVT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	4J11DA7851
Chassis No.:	GF7W0701133
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$18,139.00
Original Registration Date:	29 Apr 2021
First Registration Date:	29 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$18,139.00 90 60
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2031
PARF Rebate Amount:	\$13,604.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,309.00
COE Rebate Amount:	\$42,806.00
Total Rebate Amount:	\$56,410.00

The information contained herein is correct as at 22 Feb 2023

OK



## Post an Advertisement

Sell it yourself! Advertise it at just

**\$68 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. 90% Loan by  
GV Cars Financing at 3.28% p.a.  
Low Interest Rate  
GV Automobile Centre StarAd

Sort by Date Posted 20 results/page

5 vehicles





Mitsubishi Outlander

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Outlander		Any	Any	2021	Any	Any	Any	Available
	Mitsubishi Outlander 2.0A		\$125,800	\$14,360 /yr	06-Apr-2021	1,998 cc	31,000 km	SUV	Available
Cheapest in the market. 1 owner only. Cycle & Carriage warranty and fully serviced unit. Full loan available. Non-smoker unit. Accident f...									
Pure Motors Pte Ltd									
Posted: 20-Feb-2023									
	Mitsubishi Outlander 2.0A		\$145,777	\$16,820 /yr	26-Feb-2021	1,998 cc	-	SUV	Available
Agent Warranty/Maintained. Full loan available! Spacious and comfortable 7 Seater SUV. Excellent condition and well maintained. Buy wi...									
Se7en Motor Pte Ltd									
Posted: 01-Feb-2023									
	Mitsubishi Outlander 2.0A Style		\$133,800	\$14,600 /yr	18-Jun-2021	1,998 cc	11,024 km	SUV	Available
(highest spec style edition) 100% loan available! 1 owner, 5 years warranty and 10 years engine warranty by C&C! Timely serviced with...									
✓ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More									
1axis									
Posted: 30-Jan-2023									
	Mitsubishi Outlander 2.0A		\$128,188	\$14,590 /yr	21-Apr-2021	1,998 cc	29,500 km	SUV	Available
1 owner. Genuine low mileage. Shiny silver exterior with black leather interior. As good as brand new condition. 10 years engine warra...									
Car Vault Pte Ltd									
Posted: 13-Jan-2023									
	Mitsubishi Outlander 2.4A (For Lease)								
\$2,300/mth Large cargo space Mitsubishi Outlander is available for long-term lease. Contact us for more info or book now!									
More info about this vehicle									
	Mitsubishi Outlander 2.0A		\$136,800	\$14,880 /yr	23-Sep-2021	1,998 cc	22,000 km	SUV	Available
Beautiful Blue Outlander Up For Sale! Maintained by 1 Meticulous Owner. Popular 7 Seator SUV For Big Family And Good Fuel Consumpti...									
Posted: 13-Jan-2023									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page