



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23001922/Avy3m4	
			Date: 29/03/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBD 8936C	Veh. Inspected	SJT 3608D
	Policy No.	D22MTPCVE001828	Coverage (\$)	0.00
	Claim No.	CMTD2300734/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	21/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA PICNIC	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTEGH23B200027034	Colour	WHITE
	Odometer	192828 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TOYO	6 mm
	L/H Front Tyre	205/60 R16	TOYO	6 mm
	R/H Rear Tyre	205/60 R16	TOYO	6 mm
	L/H Rear Tyre	205/60 R16	TOYO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/02/2023	Inspection Date	21/02/2023
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	