

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS
BLK 484B CHO A CHU KANG AVE 5 #10-36
SINGAPORE 682484

Contact : 92708426, 87531283

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Distorted</i>	1	754.10	754.10
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	474.70	474.70
FRONT BUMPER RH FOGLAMP <i>Crackd</i>	1	390.60	390.60
FRONT BUMPER RH FOGLAMP GARNISH <i>Delcd</i>	1	150.10	150.10
FRONT BUMPER SIDE RETAINER L/R <i>RH and</i>	2	129.90	55 259.80
FRONT BUMPER SPONGE <i>Crackd</i>	1	127.60	127.60
FRONT HEADLAMP L/R <i>RH Crackd</i>	2	766.10	766.10 1532.20
FRONT RH FENDER <i>Buckle</i>	1	625.00	625.00
FRONT RH FENDER 'VVT-I' EMBLEM <i>Neu</i>	1	81.00	81.00
FRONT RH FENDER INNER BRACKET <i>Best</i>	1	98.00	98.00
FRONT RH FENDER INNER SHIELD <i>lon</i>	1	406.90	185 406.90
FRONT RH KNUCKLE ARM <i>Best</i>	1	703.70	703.70
FRONT RH KNUCKLE ARM BEARING <i>and</i>	1	248.90	248.90
FRONT RH LOWER ARM <i>Best</i>	1	596.00	596.00
FRONT RH SHOCK ABSORBER <i>Best</i>	1	647.80	647.80
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>Not in</i>	1	205.00	205.00
FRONT RH STABILIZER LINK <i>Best</i>	1	251.10	251.10
FRONT RH TIE ROD END <i>Best</i>	1	313.50	313.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS
BLK 484B CHOA CHU KANG AVE 5 #10-36
SINGAPORE 682484

Contact : 92708426, 87531283

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

FRONT SUPPORT PANEL	<i>Revs</i>	1	1172.50	<i>X</i>	1,172.50
FRONT WASHER TANK	<i>Del</i>	1	177.10	<i>✓</i>	177.10
FRONT WASHER TANK MOTOR		2	165.00	<i>+</i>	330.00
Subtotal before discount					9,545.60
Percentage discount 25%					2,386.40
Sub-total 1					7,159.20
FRONT RH 205/60R16 TYRE	<i>Re m</i>	1	480.00	<i>X</i>	480.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	<i>Nu</i>	1	50.00	<i>30</i>	50.00
FRONT RH SPORT RIM	<i>At</i>	1	850.00	<i>400</i>	850.00
Subtotal before discount					1,380.00
Percentage discount 0%					0.00
Sub-total 2					1,380.00
Parts-total					8,539.20

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	<i>X</i>	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>30</i>	80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	<i>220</i>	380.00
To road test driving, check and resetting wheel alignments system.	<i>80</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>700</i>	1,100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS
BLK 484B CHOA CHU KANG AVE 5 #10-36
SINGAPORE 682484

Contact : 92708426, 87531283

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

500 800.00

To apply anti-rust chemical on repaired and replaced panel.

40 100.00

Labour Total

2,680.00

Parts & Labour Total

11,219.20

*** This is a computer-generated document which requires no signature. ***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
R/S 21/02/23.
05 Days