

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Raki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS

BLK 484B CHOA CHU KANG AVE 5 #10-36

SINGAPORE 682484

Contact : 92708426, 87531283

7P Sompoo.

Veron.

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Distorted</i>	1	754.10	580 754.10
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	474.70	322 474.70
FRONT BUMPER RH FOGLAMP <i>Crackd</i>	1	390.60	318 390.60
FRONT BUMPER RH FOGLAMP GARNISH <i>Delcd</i>	1	150.10	150.10
FRONT BUMPER SIDE RETAINER L/R <i>RH and</i>	2	129.90	55 259.80
FRONT BUMPER SPONGE <i>Crackd</i>	1	127.60	127.60
FRONT HEADLAMP L/R <i>RH Crackd</i>	2	766.10	766.10 1532.20
FRONT RH FENDER <i>Crackd</i>	1	625.00	625.00
FRONT RH FENDER 'VVT-I' EMBLEM <i>new</i>	1	81.00	81.00
FRONT RH FENDER INNER BRACKET <i>Best</i>	1	98.00	98.00
FRONT RH FENDER INNER SHIELD <i>low</i>	1	406.90	185 406.90
FRONT RH KNUCKLE ARM <i>Best</i>	1	703.70	441 703.70
FRONT RH KNUCKLE ARM BEARING <i>and</i>	1	248.90	248.90
FRONT RH LOWER ARM <i>Best</i>	1	596.00	596.00
FRONT RH SHOCK ABSORBER <i>Best</i>	1	647.80	322 647.80
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>Not in</i>	1	205.00	205.00
FRONT RH STABILIZER LINK <i>Best</i>	1	251.10	121 251.10
FRONT RH TIE ROD END <i>Best</i>	1	313.50	118 313.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS
BLK 484B CHOA CHU KANG AVE 5 #10-36
SINGAPORE 682484

Contact : 92708426, 87531283

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

FRONT SUPPORT PANEL	Reps	1	1172.50	X	1,172.50
FRONT WASHER TANK	Del	1	177.10	107 ✓	177.10
FRONT WASHER TANK MOTOR	NN	2	165.00	+	330.00
Subtotal before discount					9,545.60
Percentage discount 25%					2,386.40
Sub-total 1					7,159.20
FRONT RH 205/60R16 TYRE	Re m	1	480.00	X	480.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	Nla	1	50.00	30 ✓	50.00
FRONT RH SPORT RIM	Ct	1	850.00	400 ✓	850.00
Subtotal before discount					1,380.00
Percentage discount 0%					0.00
Sub-total 2					1,380.00
Parts-total					8,539.20

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)

X 120.00

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

30 80.00

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

220 380.00

To road test driving, check and resetting wheel alignments system.

80 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

700 1,100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17/ #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SATHIAKALA D/O SIVADAS
BLK 484B CHOA CHU KANG AVE 5 #10-36
SINGAPORE 682484

Contact : 92708426, 87531283

TAX INVOICE

Repair Code : CLM15811

Date in : 18/02/2023

Vehicle Num. : SJT3608D

Model : TOYOTA PICNIC AUTO W/O ROOF RACK

Chassis/Eng# : JTEGH23B200027034/1AZH373723

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,680.00

Parts & Labour Total

11,219.20

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
h/s 21/02/23.
05 Days.

total: 5946.27
h/s: 4.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: