



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23001928/Rvp3e2

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

Date: 27/02/2023

ATTN: TEO KITTY

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHD 378U	Veh. Inspected	FBS 1568Z
Policy No.	VFX/P2413997	Coverage (\$)	0.00
Claim No.	S2M04H4I	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	21/02/2023

2. Vehicle Particulars & Condition


Make & Model	YAMAHA AEROX155 ABS CVT	c.c	155
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3SG6420LJ001891	Colour	BLACK
Odometer	43062 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80-14	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	PIRELLI	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION, O/S AND N/S BODY.



5. General Information

Accident Date	24/12/2022	Inspect Date / Time	22/02/2023 (12:19 PM)
Survey held at	FASTECH MOTORS PTE LTD 5 Soon Lee Street (Pioneer Point) #01-43 Singapore 627607		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------

Report Ref No. CS3/HSB23001928/Rvp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.