

Vehicle Damage Assessment Report for [SLP7140G]

Estimate Created: 01/05/2023 15:05 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 01/05/2023 15:23 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Vezel
Engine Type			
License Plate Number	SLP7140G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,600.00 WITH 6 WORKING
DAYS

Insurlogic 4 (01/05/2023 15:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Tailgate		1	1100.00	-20.00 %	880.00
Tailgate Emblem Vezel		1	70.00	-20.00 %	56.00
Tailgate lamp LH		1	425.00	-20.00 %	340.00
Tailgate lamp clips		1	10.00	-20.00 %	8.00
Tailgate inner trim		1	285.00	-20.00 %	228.00
Tailgate inner trim clips		1	30.00	-20.00 %	24.00
Tailgate inner lock		1	182.00	-20.00 %	145.60
Tailgate weaherstrip		1	198.70	-20.00 %	158.96
Rear windscreen moulding		1	165.80	-20.00 %	132.64
Rear windscreen inner seal		1	60.00	-20.00 %	48.00
Rear bumper		1	880.00	-20.00 %	704.00
Rear bumper side retainer		1	90.60	-20.00 %	72.48
Rear bumper clips		1	30.00	-20.00 %	24.00
RH rear corner bumper		1	195.00	-20.00 %	156.00
Rear end panel		1	595.00	-20.00 %	476.00
Rea end panel top trim		1	198.30	-20.00 %	158.64
Rea end panel top trim clips		1	20.00	-20.00 %	16.00
Spare tyre panel top board		1	306.00	-20.00 %	244.80
Spare tyre panel top tool sponge		1	285.00	-20.00 %	228.00
Rear key antena sensor		1	145.80	-20.00 %	116.64
Alarm sensor speaker		1	150.00	-20.00 %	120.00
Taillamp LH		1	495.00	-20.00 %	396.00

Parts Subtotal 4,733.76

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear windscreen sealant		1.0	60.00	0.00 %	60.00
Rear sensor		1.0	200.00	0.00 %	200.00
Body panel joint sealant		1.0	60.00	0.00 %	60.00

Materials Subtotal 320.00

Labor

Replace/RnR

Panel beating	RnR	800.00	0.00 %	800.00
Check wiring on taillamp	RnR	30.00	0.00 %	30.00
Anti Rust	RnR	60.00	0.00 %	60.00
Remove and install rear windscreen	RnR	120.00	0.00 %	120.00
Remove and install tailgate parts	RnR	60.00	0.00 %	60.00
To remove and install interior upholstery	RnR	60.00	0.00 %	60.00
Remove and install reverse camera	RnR	50.00	0.00 %	50.00
Remove and install reverse sensor	RnR	50.00	0.00 %	50.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Spare tyre panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	800.00	0.00 %	800.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,230.00

Paint Labor Subtotal 800.00

Labor Subtotal 2,030.00

Summary

Repair Cost 7,083.76

Discount(20 %) (1,416.75)

5,667.01

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 5,667.01