



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23001931/Tny3e2 Date: 04/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SFH 13A	Veh. Inspected	SMX 2971D	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS22/1250	Excess (\$)	0.00	
Assign From	ESTHER CHEAH	Assign Date	20/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDD2050402R206531	Colour	YELLOW	
Odometer	141683 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	WEST LAKE	6 mm	
L/H Front Tyre	225/45 R18	WEST LAKE	6 mm	
R/H Rear Tyre	225/45 R18	WEST LAKE	6 mm	
L/H Rear Tyre	225/45 R18	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	29/07/2022	Inspection Date	22/02/2023	
Survey held at	SV AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)REGISTRATION DATE: 21 OCT 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	