

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD
DATE: 21.02.2023

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMT676R**
MODEL : **HONDA HRV**
DATE OF ACCIDENT : 28.01.2023
TIME OF ACCIDENT : 01:20 HOURS

JHMRU1830JX202445
Eg/yan

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del d</i>	1	\$ 1,085.00	\$ 1,085.00 <i>594</i>
2	FRONT BUMPER FOG LAMP GARNISH LH <i>anled</i>	1	\$ 381.00	\$ 381.00 <i>352</i>
3	FRONT BUMPER SIDE RETAINER <i>ben</i>	2	\$ 23.00	\$ 46.00 <i>+</i>
4	HEADLAMP LH (LED) <i>abem</i>	1	\$ 1,859.40	\$ 1,859.40 <i>+</i>
5	HEADLAMP LOWER BRACKET <i>anled</i>	1	\$ 59.00	\$ 59.00 <i>+</i>
6	FRONT FENDER ARCD GARNISH LH <i>jan</i>	1	\$ 195.00	\$ 195.00 <i>+</i>
7	FRONT FENDER INNER COWLING LH	1	\$ 170.50	\$ 170.50 <i>+</i>

1005
804

TOTAL PRICE	\$ 3,795.90
LESS 20%	\$ 759.18
SUB TOTAL PRICE	\$ 3,036.72

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>an</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
2	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>2</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
3	FRONT FENDER INNER COWLING CLIP RH (SET) <i>jan</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
4	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>jan</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
5	BRAKE OIL	1	\$ 40.00	\$ 40.00 <i>+</i>

TOTAL \$ 230.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00 <i>250</i>	

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMT676R**
MODEL : **HONDA HRV**
DATE OF ACCIDENT : 28.01.2023
TIME OF ACCIDENT : 01:20 HOURS

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	260
3	WIRING CHECK	\$ 120.00	30
4	REFOCUS HEADLAMP BEAM	\$ 80.00	X
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 2,980.00

TOTAL PARTS COST : \$ 3,266.72
TOTAL LABOUR COST : \$ 2,980.00
TOTAL REPAIR COST : \$ 6,246.72

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian C
H/S 22/02/23

0320/23

total: 1364

4/5: 1.1K.

1.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: