

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 09.02.2023

TO : AIG MOTOR CLAIMS DEPTS  
VEHICLE NO : PC8121B  
MODEL : TOYOTA HIACE  
DATE OF ACCIDENT : 09.12.2023  
TIME OF ACCIDENT : 20:30 HOURS

*Xiao Tony*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                 | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT BUMPER <i>Dehd</i>                    | 1   | \$ 495.70       | \$ 495.70        |
| 2   | FRONT BUMPER FOGLAMP COVER RH <i>Neu</i>    | 1   | \$ 98.30        | \$ 98.30         |
| 3   | FRONT BUMPER LOWER GRILLE <i>Neu</i>        | 1   | \$ 196.70       | \$ 196.70        |
| 4   | FRONT BUMPER SIDE RETAINER <i>Conld RH</i>  | 2   | \$ 180.00       | \$ 360.00        |
| 5   | FRONT BUMPER CENTER BEAM <i>Neu</i>         | 1   | \$ 385.00       | \$ 385.00        |
| 6   | FRONT BUMPER REINFORCEMENT <i>Neu</i>       | 1   | \$ 438.50       | \$ 438.50        |
| 7   | HEADLAMP (LED) RH <i>Conld</i>              | 1   | \$ 2,536.20     | \$ 2,536.20      |
| 8   | FRONT AIR CLEANER <i>Conld</i>              | 1   | \$ 576.70       | \$ 576.70        |
| 9   | FRONT WIRE SOCKET HOLDER RH <i>Neu</i>      | 1   | \$ 146.40       | \$ 146.40        |
| 10  | FRONT GRILLE (COMPLETE SET) <i>Neu</i>      | 1   | \$ 789.30       | \$ 789.30        |
| 11  | FRONT DOOR STEP PANEL GARNISH RH <i>Neu</i> | 1   | \$ 198.10       | \$ 198.10        |

*210740*

*1580.55*

TOTAL PRICE \$ 6,220.90  
LESS 25% \$ 1,555.23  
SUB TOTAL PRICE \$ 4,665.68

| S/N | DESCRIPTION                                            | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--------------------------------------------------------|-----|-------------|--------------|
| 1   | FRONT BUMPER CLIP (SET) <i>Neu</i>                     | 1   | \$ 80.00    | \$ 80.00     |
| 2   | FRONT BUMPER LOWER GRILLE CLIP (SET) <i>Neu</i>        | 1   | \$ 50.00    | \$ 50.00     |
| 3   | FRONT DOOR STEP PANEL GARNISH CLIP RH (SET) <i>Neu</i> | 1   | \$ 40.00    | \$ 40.00     |
| 4   | FRONT GRILLE CLIP (SET) <i>Neu</i>                     | 1   | \$ 30.00    | \$ 30.00     |

*30*

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **PC8121B**  
MODEL : **TOYOTA HIACE**  
DATE OF ACCIDENT : 09.12.2023  
TIME OF ACCIDENT : 20:30 HOURS

**TOTAL \$ 200.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

| S/N | JOB DESCRIPTION                                                                                | PRICE     | ADJUSTED COST |
|-----|------------------------------------------------------------------------------------------------|-----------|---------------|
| 1   | PANEL BEATING, REMOVING AND REPLACING PARTS                                                    | \$ 800.00 | 300.          |
| 2   | SPRAY PAINTING TO AFFECTED AREA                                                                | \$ 800.00 | 200.          |
| 3   | TUFF COAT                                                                                      | \$ 250.00 | x             |
| 4   | REFOCUS HEADLAMP BEAM                                                                          | \$ 60.00  | x             |
| 5   | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | x             |

**TOTAL \$ 2,090.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 4,865.68  
TOTAL LABOUR COST : \$ 2,090.00  
TOTAL REPAIR COST : \$ 6,955.68

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li  
r/s 09/02/23.  
03 Days.

Total: 2110.55

r/s: 1650 ✓