## **HD Perfect Autowork Pte Ltd**

Company Rea No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit Singapore 415875

Tel: 6341 6789 Fax: 6341 6778 E-mail: hdperfectautowork@gmail.com



AUTOWORK PTE LTD

**DATE**: 20.02.2023

TO

: INCOME MOTOR CLAIMS DEPTS

VEHICLE NO

: SMG78K

MODEL

: VOLKWAGEN TOURAN

DATE OF ACCIDENT

: 19.02.2023

TIME OF ACCIDENT

: 16:10 HOURS

Venon

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION		QTY	-	UNIT LIST		PRICE	
1	FRONT DOOR VIEW MIRROR RH	Ryd	1	\$	1,856.20	\$	1,856.20	
2	FRONT DOOR RH Men		1	\$	2,565.98	\$	2,565.98	

1385 1315.75

TOTAL PRICE LESS 5%

4,422.18

WVGZZZZITZLWOSSY96

SUB TOTAL PRICE

Ś

221.11 4,201.07

## CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 500.00	(0)
2	TO SPRAY PAINT	\$ 500.00	100
3	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

200

- 1385-

TOTAL

1,250.00

## **ESTIMATE REPORT**

TOTAL PARTS COST : \$ 4,201.07 TOTAL LABOUR COST : \$ 1,250.00 TOTAL REPAIR COST : S 5,451.07

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

SERVICE ADVISOR **IRENE** 

HP: 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign ire:



Adrin L