LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 23 Feb 2023

Preliminary Advice

 Vehicle No
 : EV9922E
 Accident Date
 : 17/02/2023

 Make
 : VOLVO S60
 Policy No.
 : SP2001203659

 Assignment Date
 : 22/02/2023
 Excess
 : \$\$600.00

Date of Inspection : 22/02/2023 Est. Duration of Repair : 5

Inspection At : WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD)

249 ALEXANDRA ROAD SINGAPORE 159935

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,903.60
Revised Amount	:S\$	8,908.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,908.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

 Pre-Accident Value
 :S\$ 124,000.00

 COE / PARF Rebate
 :S\$ 52,537.00

Salvage Value :S\$

Margin for Repair :S\$ 71,463.00

Remarks

(x)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair on part by parts basis.due to the workshop is agent workshop.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.