

## Huey Yon (LKKAuto)

---

**From:** Huey Yon (LKKAuto)  
**Sent:** Tuesday, 28 March 2023 11:56 AM  
**To:** Richmond Ho; Shiau Chan (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Dear Richmond,

Without prejudice

We will be advising our principal a cost of repair of \$12,366.09 before excess \$600.00 and GST with 5 days of repair, subject to their approval.

Best Regards,  
Huey Yon | Case Handler  
LKK Auto Consultants  
phone: 6256-3561 | email: [hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Richmond Ho <[richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)>  
**Sent:** Tuesday, March 28, 2023 10:21 AM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023  
**Importance:** High

Hi Shiau Chan

Please see attached for the final bill.

**Richmond Ho**  
Senior Service Consultant  
Body & Paint – Insurance Claim



**Wearnes Automotive Pte Ltd**  
249 Alexandra Road Singapore 159935  
D (65) 6430 4890 M (65) 9176 8543  
[www.wearnesauto.com](http://www.wearnesauto.com) [richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Friday, 3 March 2023 2:52 pm  
**To:** Richmond Ho <[richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Dear Richmond,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Richmond Ho <[richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)>

**Sent:** Friday, March 3, 2023 9:05 AM

**To:** Huey Yon (LKKAuto) <[hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Hi

Please see attached, thanks

**Richmond Ho**

Senior Service Consultant

Body & Paint – Insurance Claim



**Wearnes Automotive Pte Ltd**

249 Alexandra Road Singapore 159935

D (65) 6430 4890 M (65) 9176 8543

[www.wearnesauto.com](http://www.wearnesauto.com) [richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.*

*If you have received it in error, please notify us immediately by reply email and then delete this message from your system.*

*Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

---

**From:** Richmond Ho

**Sent:** Thursday, 2 March 2023 1:49 pm

**To:** Huey Yon (LKKAuto) <[hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** Re: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Hi Huey Yan

There are additional parts damaged which I had forwarded the photos to your surveyor Edward. Kindly let us know if re-survey is required or can we proceed repair.

Vehicle is at 2 Jalan Pesawat.

Richmond Ho

Senior Service Consultant

Wearnes Automotive Pte. Ltd.

249 Alexandra Road Singapore 159935

Mobile. (65) 9176 8543

Direct. (65) 6430 4890

website. [www.wearnesauto.com](http://www.wearnesauto.com)

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

On 23 Feb 2023, at 15:24, Huey Yon (LKKAuto) <[hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)> wrote:

Dear Richmond,

Re-send

As instructed by our client, please proceed to repair the insured vehicle **EV 9922E (Excess \$600.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Huey Yon** | case handler

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Fax: 62564315 email: [hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

---

**From:** Huey Yon (LKKAuto)

**Sent:** Thursday, February 23, 2023 3:22 PM

**To:** [richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **EV 9922E (Excess \$600.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Huey Yon** | case handler

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Fax: 62564315 email: [hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

<Mark estimate.pdf>