Huey Yon (LKKAuto)

From: Huey Yon (LKKAuto)

Sent: Thursday, 23 February 2023 3:23 PM **To:** 'richmond.ho@wearnes.com'

Cc: SUF

Subject: RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Attachments: Mark estimate.pdf

Dear Richmond,

Re-send

As instructed by our client, please proceed to repair the insured vehicle EV 9922E (Excess \$600.00/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Huey Yon | case handler **LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Huey Yon (LKKAuto)

Sent: Thursday, February 23, 2023 3:22 PM

To: richmond.ho@wearnes.com **Cc:** SUR <sur@lkkauto.com>

Subject: RE: EV 9922E DESKTOP SURVEY-DOA: 17/02/2023

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle EV 9922E (Excess \$600.00/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Huey Yon | case handler **LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933