

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23001962/SQY3Q2**Date:** 23/05/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ001269
Claimant Vehicle No :	SHC8986S	Insured Vehicle No :	GBH2549E
Date of Loss:	18/02/2023	Nature of Claim:	TP
		Claim No:	M2301169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8986S	Engine No:	D4FDGU614051
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU089821
Reg. Date:	19/05/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,315.56	2,696.12	2,619.44	49.28
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,170.00	1,510.00	660.00	30.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,496.56	4,217.12	3,279.44	43.75
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	7,496.56	3,350.00	4,146.56	55.31
+ GST 8.00/8.00% (S\$)	599.72	268.00	331.72	55.31
Nett Amount (S\$)	8,096.28	3,618.00	4,478.28	55.31

INSPECTION

Date of Assignment:	21/02/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/02/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8986S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Dented	2,256.40 FL	*2,256.40 FL
2	1		*FRT DOOR REGULATOR LH	Not Necessary	776.80 FL	*- FL
3	1		*FRT DOOR POWER MOTOR LH	Not Necessary	296.40 FL	*- FL
4	1		*FRT DOOR MIRROR LH	Broken	670.00 FL	*670.00 FL
5	1		*RR DOOR LH 2201.1	Repair	2,201.10 FL	*- FL
6	1		*RENEW ADVERTISWEMENT STICKER	Necessary	200.00 F	*200.00 F
7	1		*REAR DOOR COMFORTDELGRO & APPS STICKER	Necessary	80.00 F	*80.00 F
8	1		*FRT DOOR COMFORT LOGO LH	Necessary	75.00 F	*75.00 F
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					6,555.70	3,281.40
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,240.14	585.28
Total Parts (\$\$)					5,315.56	2,696.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	560.00
2	SPRAY PAINTING CHARGE	New	850.00	750.00
3	TRANSFER OF DOOR FRT & RR RH	New	240.00	80.00
4	CHECK ALL LIGHTING	New	60.00	30.00
5	TUFF KOTE	New	60.00	30.00
6	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			2,170.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >