



CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

1 of 2

BE 11101165

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
A.	Spare Parts				
1	Rear Bumper <i>Dented</i>	1	\$860.00	\$860.00	—
2	Rear Bumper side retainer LH <i>Dented</i>	1	\$18.00	\$18.00	—
3	Rear LH Fender <i>Dented</i>	1	\$1,263.80	\$1,263.80	— 1025
4	Rear LH Door <i>Dented</i>	1	\$1,096.40	\$1,096.40	—
5	Rear LH Door rubber <i>new</i>	1	\$105.00	\$105.00	x
6	Rear LH door power window regulator <i>Dented</i>	1	\$285.00	\$285.00	✓
7	Rear LH door power window regulator motor <i>new</i>	1	\$453.00	\$453.00	x
8	Rear LH rear door lock <i>Dented</i>	1	\$259.00	\$259.00	—
9	Front LH Door <i>Repair</i>	1	\$968.30	\$968.30	x.
10	Petrol Cover <i>new</i>	1	\$230.00	\$230.00	x.
			Total	\$5,538.50	
			Less 20%	\$1,107.70	
			Sub Total 1	\$4,430.80	

3543.4

2834.72



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 17-02-23

Xiao Tray

CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Our Customer : LEE CHARN KHOON

Vehicle No : SGK 1623 E

Model : HONDA EDIX

Manufacture Year : 2006

Date of Accident : 12-02-23

Total Estimate Repair Days : 10 DAYS

Total Pages : 2

2 of 2

Re: Repair Estimate For Third Party Claim against SFA9995

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
A.	Spare Parts (S/Nett)				
1	Rear LH Rim <i>ct</i>	1		\$1,000.00	<i>400</i>
2	Bumper Clip <i>nr</i>	10	\$5.50	\$55.00	<i>* 30</i>
	Sub-Total 2			\$1,055.00	
	Total for Parts			\$5,485.80	
B.	Labour				
1	To check wiring.			\$80.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,000.00	<i>800</i>
3	Spray painting all affected parts & areas.			\$1,200.00	<i>800</i>
4	Labour to remove, refit and reinstall rear windscreen			\$120.00	<i>60</i>
5	To check align wheel with computerised wheel alignment			\$80.00	<i>60</i>
6	To remove, refit rear windscreen			\$200.00	<i>*</i>
	Total Labour			\$3,680.00	
	Total Repair Cost			\$9,165.80	

Adrian Lj
h/s 17/02/23.
07 Days

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Candice Yee

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Supplementary: 375.20
total: 5389.92
4/s: 4.31K



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

Date : 27-03-23

CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Our Customer : LEE CHARN KHOON

Vehicle No : SGK 1623 E

Model : HONDA EDIX

Manufacture Year : 2006

Date of Accident : 12-02-23

Total Estimate Repair Days : 10 days

Total Pages : 1

Attn: Motor Claims Department

Tel: 6389 6111

Re: Supplementry repair For Third Party Claim against SFA999S

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
A.	Spare Parts				
1	Wheel Hub Bearing <i>and.</i>	1		\$488.88	<i>394</i>
	Total			\$488.88	
	Less 20%			\$97.78	
	Sub Total 1			\$391.10	
B.	Labour				
1	Labour - Wheel hub bearing.			\$100.00	<i>60</i>
	Total Labour			\$100.00	
	Total Repair Cost			\$491.10	

Adrian
27/03/23
394
315.20
Supplementary: 375.20

Yours faithfully,

Candice Yee

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No