

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 01 Mar 2023

Preliminary Advice

Vehicle No	: SMV2226H	Accident Date	: 04/02/2023
Make	: VOLKSWAGEN TOURAN	Policy No.	: SP2002854049-01
Assignment Date	: 22/02/2023	Excess	: S\$600.00
Date of Inspection	: 27/02/2023	Est. Duration of Repair	: 7
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,188.35
Revised Amount	:S\$	9,920.81
Check Items (Estimated)	:S\$	496.26
Total	:S\$	10,417.07

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	142,000.00
COE / PARF Rebate	:S\$	50,400.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,600.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check