



ESTIMATE

DATE OF ACCIDENT : 16/02/2023
VEHICLE : SMQ9958J
MAKE & MODEL : HONDA VEZEL
INSURANCE : ALLIANZ
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	BONNET <i>Dented</i> <i>450</i>	\$ 2300 <i>950</i>
2.	BONNET INSULATOR <i>new</i>	\$ 210 <i>+</i>
3.	BONNET WEATHERSTRIP <i>cut</i>	\$ 330 <i>✓</i> <i>45</i>
4.	BONNET LOCK <i>Damaged</i>	\$ 320 <i>✓</i> <i>95</i>
5.	BONNET HINGE - LEFT & RIGHT <i>Both</i>	\$ 250 <i>✓</i> <i>110</i>
6.	FRONT FENDER - LEFT <i>2 Repairs</i>	\$ 980 <i>+</i>
7.	FRONT FENDER - RIGHT	\$ 980 <i>+</i>
8.	FRONT FENDER BRACKET - LEFT & RIGHT <i>new</i>	\$ 300 <i>+</i>
9.	HEADLIGHT - LEFT <i>cracked</i> <i>850</i>	\$ 2300 <i>1500</i>
10.	HEADLIGHT - RIGHT <i>new</i>	\$ 2300 <i>+</i>
11.	HEADLIGHT TOP BRACKET - RIGHT <i>new</i>	\$ 110 <i>+</i>
12.	HEADLIGHT TOP BRACKET - LEFT <i>new</i>	\$ 100 <i>+</i>
13.	HEADLIGHT LOWER BRACKET - RIGHT <i>new</i>	\$ 110 <i>+</i>



JACK CARS

DRIVE WITH ASSURANCE

14.	HEADLIGHT LOWER BRACKET - LEFT ?	25	\$ 110 ?	50
15.	FRONT BUMPER Dehd	400	\$ 900 -	990
16.	FRONT BUMPER CHROME GARNISH cruld	200	\$ 350 -	280
17.	FRONT BUMPER GRILLE cruld	250	\$ 520 -	510
18.	FRONT BUMPER GRILLE GARNISH cruld	130	\$ 380 -	320
19.	FRONT BUMPER LOWER GRILLE New		\$ 410 +	
20.	FRONT BUMPER LOWER LIPS New		\$ 280 +	
21.	FRONT BUMPER BRACKET - LEFT & RIGHT 2H Bnd		\$ 200 -	35
22.	FRONT BUMPER SPONGE New		\$ 180 +	
23.	FOG LAMP New		\$ 690 +	
24.	FOG LAMP COVER Lt	55	\$ 310 -	175
25.	INTAKE MANIFOLD New		\$ 2500 +	
26.	FRONT SUPPORT PANEL Repair		\$ 1800 +	
27.	FRONT SUPPORT PANEL TOP COVER ?	70	\$ 230 ?	195
28.	FRONT SUPPORT BEAM Best	200	\$ 690 -	500
29.	CENTRE BRACKET cruld		\$ 310 -	
2915 110% : 3206.50				
SPECIAL NETT				
1.	REAR NUMBER PLATE & COVER Best		\$ 95 -	60
2.	CLIPS , RIVETS & SCREWS New		\$ 100 -	30
3.	RADAR SENSOR New		\$ 720 -	



JACK CARS

DRIVE WITH ASSURANCE

4.	"HONDA" EMBLEM <i>Nur</i>	25	\$ 95 - <i>75</i>
		115	
	LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 2500 <i>600</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		\$ 2000 <i>800</i>
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE		\$ 250 <i>50</i>
4.	TO REMOVE & REINSTALL SENSORS	1490	\$ 200 <i>*</i>
5.	ANTI RUST TREATMENT		\$ 200 <i>40</i>
6.	PROGRAMMING (HEADLAMP & RADAR SENSOR)		\$ 700 <i>*</i>
	<i>Total: 4811.50</i>	PARTS + 10 %:	\$ 22,495
	<i>L/S: 3850</i>	SPECIAL NETT :	\$ 1,010
		LABOUR :	\$ 5,850
		TOTAL :	\$ 29,355
		8% GST :	\$ 2,348.40
		GRAND TOTAL :	\$ 31,703.40

Jack Cars Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

Adrian Lj
h/s 23/02/23.
05 days.
Excess \$2K.
Not Authorized.