



Final Report

Estimate No. : **b1 65089**
Date Estimated : **21/02/2023**
Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

ZHANG ZUGUANG
5 Yishun Close
#05-10

Singapore 768006

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNF8037U	WBA32AN0207K92941	23/06/2022	216i Gran Coupe	10460

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front LH door, rear LH door, LH wingmirror assembly, door weatherstrip include making good the rear LH fender, LH side sill trim, LH 'C' pillar and carrying out necessary repairs caused by the accident	5,525.00		5,525.00
To respray rear LH fender, rear LH door, front LH door, LH side sill trim, LH 'C' pillar, LH wingmirror cover and door handles (x2)	5,209.00		5,209.00
To carry out body cavity preservation (x2) (Per panel)	224.00		224.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (x1)	504.00		504.00
To replace wheel rim include balancing (x1)	90.00		90.00
To remove and install rear LH door fixed window glass to facilitate repairs	338.00		338.00
To conduct water leak tests	75.00		75.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function (x2)	1,008.00		1,008.00

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W





Final Report

To check electrical wiring system and lightings at the LH section for proper function	168.00	168.00
---------------------------------------------------------------------------------------	--------	--------

Sundries	150.00	150.00
----------	--------	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 7.5X17 DOUBLE SPK 549	977.35	1.00	0.00	977.35
FRT LH DOOR	1,194.55	1.00	0.00	1,194.55
REAR LH DOOR	1,194.55	1.00	0.00	1,194.55
LH OUTSIDE MIRROR HEATED WITH MEMORY	859.90	1.00	0.00	859.90
LH OUTSIDE MIRROR COVER CAP PRIMED	133.90	1.00	0.00	133.90
(S/L) DOOR WEATHERSTRIP	143.30	2.00	0.00	286.60
# CLIP ROOF FRAME STRIP	1.95	7.00	0.00	13.65

SUPPLEMENTARY ITEMS

Total Labour :	13,291.00
Total Parts :	4,660.50
Total Labour & Parts (before GST) :	17,951.50
Deduction for Excess :	
Total Repair Costs less Excess:	17,951.50
GST @8%:	1,436.12
Grand Total :	19,387.62

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

