



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF23001971/Kny3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675			Date:	17/04/2023
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 1930G	Veh. Inspected	SND 1242A	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2023/007	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	21/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MR053REH604599145	Colour	METALLIC SILVER	
Odometer	37317 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	8 mm	
L/H Front Tyre	205/55 R16	FALKEN	8 mm	
R/H Rear Tyre	205/55 R16	FALKEN	8 mm	
L/H Rear Tyre	205/55 R16	FALKEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/01/2023	Inspection Date	22/02/2023	
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	