

ASS. REC. BY:

REF:

SPF / 230019711kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 1242A

Yr Regn:

01, 20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c

1598

Colour

M. Piler

A/C:

Insured / Std / NI / NA

Sp. Reading

37317

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053RE11604599145

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

13/1/23

D.O.I.

22/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Will send GIA over.

Date/Time, File Pass to?



: Prell. Report

Date/Time, File Return to?



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

F. & M.

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

CHASSIS NO: MR053REH604599145

CHASSIS NO: MR053REH604599145		REPAIRER'S ESTIMATE(S\$)	
DESCRIPTION			
PARTS (LIST ITEMS)			
REAR DOOR LHS		N \$	1,050.00 X
ROCKER PANEL LHS		N \$	400.00 X
REAR FENDER LHS		N \$	990.00 ✓
REAR FENDER INNER SHIELD LHS		R \$	80.00 X
REAR BUMPER		R \$	550.00 X
		25%	\$ 3,070.00
			\$ 767.50
			\$ 2,302.50
SPECIAL NETT ITEMS			
REAR BUMPER CLIPS 1 SET			\$ ~ 60.00 ✓
Total		\$	60.00
	TOTAL PARTS	\$	2,362.50

Not waited
Penny for Pains

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	300/
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	750/
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ~ 100.00	X
4	To provide anti-rust treatment on affected areas	\$ ~ 100.00	X
5	Dignostic Check	\$ ~ 100.00	X
6	Alignment Check	\$ 100	60/
	Labour Total :	\$ 3,500.00	
	TOTAL (PARTS & LABOUR):	\$ 5,862.50	