

VEHICLE NO: SND1242A

MODEL: TOYOTA ALTIS

CHASSIS NO: MR053REH604599145

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>			
REAR DOOR LHS		N	\$ 1,050.00 X
ROCKER PANEL LHS		N	\$ 400.00 X
REAR FENDER LHS		N	\$ 990.00 X
REAR FENDER INNER SHIELD LHS		R	\$ 80.00 X
REAR BUMPER		R	\$ 550.00 X
			</

Not withaird
 Penny After Pain
 3 days @ 1110p

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	300/
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	750/ 600/
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ~ 100.00	X
4	To provide anti-rust treatment on affected areas	\$ ~ 100.00	X
5	Dignostic Check	\$ ~ 100.00	X
6	Alignment Check	\$ 100	60/
	Labour Total :	\$ 3,500.00	
	TOTAL (PARTS & LABOUR):	\$ 5,862.50	