

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKQ5731X

Make & Model: Volkswagen Jetta

Chassis number: WVVZZZ16ZEN063597

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ 1,973.00
2	Bootlid centre emblem	1	\$ 97.00
3	Bootlid "Jetta" emblem	1	\$ 68.00
4	Bootlid "TSI" emblem	1	\$ 59.00
5	Bootlid RH lamp	1	\$ 286.00
6	Bootlid LH lamp	1	\$ 286.00
7	Bootlid lock	1	\$ 201.00
8	Bootlid inner trim	1	\$ 268.00
9	Bootlid inner trim clips	1set	\$ 80.00
10	Rear bumper <i>CRA</i>	1	\$ 1,276.00
11	Rear bumper tow cover	1	\$ 34.00
12	Rear bumper clips <i>MCC</i>	1set	\$ 80.00
13	Rear bumper lower skirt <i>CRAC</i>	1	\$ 489.00
14	Rear bumper RH reflector	1	\$ 73.00
15	Rear bumper LH reflector	1	\$ 73.00
16	Rear bumper RH side retainer	1	\$ 86.00
17	Rear bumper LH side retainer	1	\$ 86.00
18	Rear bumper centre bracket <i>CRA</i>	1	\$ 83.00
19	Rear bumper RH side attachemnt	1	\$ 87.00
20	Rear bumper LH side attachment	1	\$ 87.00
21	Rear bumper reinforcement	1	\$ 621.00
22	Rear bumper lower cover <i>CRAC - missing</i>	1	\$ 93.00
23	End panel <i>dent</i>	1	\$ 1,299.00
24	End panel inner garnish	1	\$ 167.00
25	End panel inner garnish clips	1set	\$ 60.00
26	RH taillamp assy	1	\$ 505.00
27	RH taillamp lower bracket	1	\$ 65.00
28	LH taillamp assy	1	\$ 505.00
29	LH taillamp lower bracket	1	\$ 65.00
30	Rear RH fender inner trim	1	\$ 187.00
31	Rear RH fender inner trim clips	1set	\$ 70.00
32	Rear LH fender inner trim	1	\$ 187.00
33	Rear LH fender inner trim clips	1set	\$ 70.00
34	Spare tyre panel upper cover board	1	\$ 376.00
35	Exhaust silencer	1	\$ 953.00
36	Exhaust silencer gasket	1	\$ 43.00

\$ 11,038.00

Parts less 10% \$ 1,103.80

Total \$ 9,934.20

No.	Special Nett Items	Qty	Amount S\$
1	Rear bumper reverse sensor	1set	\$ 350.00
2	End panel joint sealant	1	\$ 80.00

1012

30
485200
60

3	Rear number plate	1	\$	80.00	X
			Total:	\$	510.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,500.00	400
2	Spray painting on affected areas and panels	\$ 1,300.00	400
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	40
5	Remove and reinstall bootlid reverse camera to assist repair	\$ 100.00	30 X
6	Remove and replace bootlid inner mechanism to new bootlid	\$ 120.00	X
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00	30
8	Remove and replace rear inner trims and garnish to assist repair	\$ 220.00	X
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 150.00	X
		Total:	\$ 3,670.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

4 days

L/S

23/2/23

Infm

Spare Parts: \$ 9,934.20
Special Nett: \$ 510.00
Labour: \$ 3,670.00

Total Amount: \$ 14,114.20

bpm