

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKQ5731X

Make & Model: Volkswagen Jetta

Chassis number: WVVZZZ16ZEN063597

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid X nn	1	\$ 1,973.00
2	Bootlid centre emblem X nn	1	\$ 97.00
3	Bootlid "Jetta" emblem X nn	1	\$ 68.00
4	Bootlid "TSI" emblem X nn	1	\$ 59.00
5	Bootlid RH lamp X nn	1	\$ 286.00
6	Bootlid LH lamp X nn	1	\$ 286.00
7	Bootlid lock X nn	1	\$ 201.00
8	Bootlid inner trim X nn	1	\$ 268.00
9	Bootlid inner trim clips X nn	1set	\$ 80.00
10	Rear bumper CBA X nn	1	\$ 1,276.00
11	Rear bumper tow cover X nn	1	\$ 34.00
12	Rear bumper clips MCC X nn	1set	\$ 80.00
13	Rear bumper lower skirt ann X crac nn	1	\$ 489.00
14	Rear bumper RH reflector X nn	1	\$ 73.00
15	Rear bumper LH reflector X nn	1	\$ 73.00
16	Rear bumper RH side retainer X nn	1	\$ 86.00
17	Rear bumper LH side retainer X nn	1	\$ 86.00
18	Rear bumper centre bracket crn X nn	1	\$ 83.00
19	Rear bumper RH side attachemnt X nn	1	\$ 87.00
20	Rear bumper LH side attachment X nn	1	\$ 87.00
21	Rear bumper reinforcement X nn	1	\$ 621.00
22	Rear bumper lower cover crn X nn	1	\$ 93.00
23	End panel pent X nn	1	\$ 1,299.00
24	End panel inner garnish X nn	1	\$ 167.00
25	End panel inner garnish clips X nn	1set	\$ 60.00
26	RH taillamp assy X nn	1	\$ 505.00
27	RH taillamp lower bracket X nn	1	\$ 65.00
28	LH taillamp assy X nn	1	\$ 505.00
29	LH taillamp lower bracket X nn	1	\$ 65.00
30	Rear RH fender inner trim X nn	1	\$ 187.00
31	Rear RH fender inner trim clips X nn	1set	\$ 70.00
32	Rear LH fender inner trim X nn	1	\$ 187.00
33	Rear LH fender inner trim clips X nn	1set	\$ 70.00
34	Spare tyre panel upper cover board X nn	1	\$ 376.00
35	Exhaust silencer X nn	1	\$ 953.00
36	Exhaust silencer gasket X nn	1	\$ 43.00

Parts less 10% \$ 1,103.80
 Total \$ 9,934.20

No.	Special Nett Items	Qty	Amount S\$
1	Rear bumper reverse sensor	1set	\$ Shorted 350.00
2	End panel joint sealant	1	\$ nec 80.00

