

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SKQ5731X

Make & Model: Volkswagen Jetta

Chassis number: WVVZZZ16ZEN063597

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid X nn	1	\$ 1,973.00
2	Bootlid centre emblem X nn	1	\$ 97.00
3	Bootlid "Jetta" emblem X nn	1	\$ 68.00
4	Bootlid "TSI" emblem X nn	1	\$ 59.00
5	Bootlid RH lamp X nn	1	\$ 286.00
6	Bootlid LH lamp X nn	1	\$ 286.00
7	Bootlid lock X nn	1	\$ 201.00
8	Bootlid inner trim X nn	1	\$ 268.00
9	Bootlid inner trim clips X nn	1set	\$ 80.00
10	Rear bumper CBA X nn	1	\$ 1,276.00
11	Rear bumper tow cover X nn	1	\$ 34.00
12	Rear bumper clips MCC X nn	1set	\$ 80.00
13	Rear bumper lower skirt ann X nn	1	\$ 489.00
14	Rear bumper RH reflector X nn	1	\$ 73.00
15	Rear bumper LH reflector X nn	1	\$ 73.00
16	Rear bumper RH side retainer X nn	1	\$ 86.00
17	Rear bumper LH side retainer X nn	1	\$ 86.00
18	Rear bumper centre bracket CBA X nn	1	\$ 83.00
19	Rear bumper RH side attachemnt X nn	1	\$ 87.00
20	Rear bumper LH side attachment X nn	1	\$ 87.00
21	Rear bumper reinforcement X nn	1	\$ 621.00
22	Rear bumper lower cover stax X nn	1	\$ 93.00
23	End panel pent X nn	1	\$ 1,299.00
24	End panel inner garnish X nn	1	\$ 167.00
25	End panel inner garnish clips X nn	1set	\$ 60.00
26	RH taillamp assy X nn	1	\$ 505.00
27	RH taillamp lower bracket X nn	1	\$ 65.00
28	LH taillamp assy X nn	1	\$ 505.00
29	LH taillamp lower bracket X nn	1	\$ 65.00
30	Rear RH fender inner trim X nn	1	\$ 187.00
31	Rear RH fender inner trim clips X nn	1set	\$ 70.00
32	Rear LH fender inner trim X nn	1	\$ 187.00
33	Rear LH fender inner trim clips X nn	1set	\$ 70.00
34	Spare tyre panel upper cover board X nn	1	\$ 376.00
35	Exhaust silencer X nn	1	\$ 953.00
36	Exhaust silencer gasket X nn	1	\$ 43.00

Parts less 10% \$ 11,038.00 3122
Total \$ 1,103.80 -10%
\$ 9,934.20 2809.80

No.	Special Nett Items	Qty	Amount S\$
1	Rear bumper reverse sensor	1set	\$ Shorted 350.00
2	End panel joint sealant	1	\$ nec 80.00

3	Rear number plate	1	\$	nn 80.00	X
Total:			\$	510.00	260

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,500.00	400
2	Spray painting on affected areas and panels	\$ 1,300.00	400
3	Check wiring and lighting system on affected areas	\$ 80.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 100.00	40
5	Remove and reinstall bootlid reverse camera to assist repair	\$ 100.00	30 X
6	Remove and replace bootlid inner mechanism to new bootlid	\$ 120.00	X
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00	30
8	Remove and replace rear inner trims and garnish to assist repair	\$ 220.00	X
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 150.00	X
Total:		\$ 3,670.00	900

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

4 days

L/S

23/2/23

Infm

Spare Parts: \$ 9,934.20 3969.80
Special Nett: \$ 510.00
Labour: \$ 3,670.00 L/S - 3175.84
Total Amount: \$ 14,114.20 = 3200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: