

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001977/KQP3Q2**Date:** 02/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00084842203
Claimant Vehicle No :	SMP7391L	Insured Vehicle No :	GBG4340G
Date of Loss:	11/01/2023	Nature of Claim: TP	Claim No: SNM23D201384/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7391L		
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Engine No:	G4FGGU193584
Reg. Date:	29/08/2016 (Man. Year: 2016)	Chassis No:	KMHD841CMHU199855
Colour:	Metallic Silver	Odometer:	336291 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Arivo 8 mm	Rear Left Side:	Arivo 9 mm
Front Right Side:	Arivo 8 mm	Rear Right Side:	Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,814.56	0.00	1,814.56	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,000.00	850.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,664.56	1,000.00	2,664.56	72.71

INSPECTION

Date of Assignment:	24/02/2023	Ngs Motorsport Pte Ltd - Ang Mo Kio (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #02-01 AMK AutoPoint Singapore 568047
Date Inspected:	23/02/2023 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP7391L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Repair	486.80 FL	*- FL
2	1		*MIRROR RH	Repair	875.40 FL	*- FL
3	1		*FRT BUMPER	Repair	544.60 FL	*- FL
4	1		*LOWER SKIRT ,FRT BUMPER	Repair	278.90 FL	*- FL
5	1		*FRT DOOR ASSY (NPA)	Repair	0.00 FL	*- FL
6	12		*CLIP ,FENDER SHIELD	Not Necessary	66.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,251.70	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					437.14	0.00
Total Parts (\$\$)					1,814.56	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS.STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL INACCORDENCE WITH FACTORY SPECIFICATIONS.REPLACE/REPOSITION DAMAGED PARTS,REFIT ALIGN INTO POSITION ,REFIX ALL NECESSARY COMPONENTS /ATTACHMENTS	New	800.00	300.00
2	SPRAY PAINT ON REPLACE /REPAIR BODY ,SPORT RIM PARTS	New	1,000.00	680.00
3	TO REMOVE/REFIT WIRE HARNESS ,ALL RELATED CONNECTOR CHECK PROPER FUNCTION	New	50.00	20.00
Gross Labour Cost (S\$)			1,850.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >