



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI23001989/Rqy3m4 Date: 18/05/2023 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	WC 5617A	Veh. Inspected	SLQ 6315X
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D00022303	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	22/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU903562198	Colour	WHITE
	Odometer	330866 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	KUMHO	6 mm
	L/H Front Tyre	195/65 R15	KUMHO	6 mm
	R/H Rear Tyre	195/65 R15	KUMHO	6 mm
	L/H Rear Tyre	195/65 R15	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/02/2023	Inspection Date	22/02/2023
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	