

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 05 Jul 2023

**Preliminary Advice**

Insured Vehicle No	: XD5762X	Accident Date	: 03/02/2023
TP Vehicle No	: SMM8441K	Assignment Date	: 22/02/2023
Make	: BMW 528I	Est. Duration of Repair	: 4
Date of Inspection	: 23/02/2023		
Inspection At	: 4RENSIC MOTORS PTE LTD (HQ) 8 KAKI BUKIT AVE 4, #01-50, PREMIER @ KAKI BUKIT SINGAPORE 415875		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,042.25
Revised Amount	:S\$	8,962.68
Check Items (Estimated)	:S\$	212.14
Total	:S\$	9,174.82

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.