

Vehicle Damage Assessment Report for [SMZ5812A]

Estimate Created: 11/04/2023 15:50 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 11/04/2023 16:02 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Vezel
Engine Type			
License Plate Number	SMZ5812A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$7,450.00 WITH 5 WORKING
DAYS

Insurlogic 4 (11/04/2023 16:02)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Bonnet		1	892.10	-20.00 %	713.68
Bonnet hinges		2	85.50	-20.00 %	136.80
Bonnet inner lock		1	166.50	-20.00 %	133.20
Bonnet inner lock bracket		1	78.50	-20.00 %	62.80
Headlamp		2	2580.50	-20.00 %	4,128.80
Headlamp chrome		2	185.50	-20.00 %	296.80
Headlamp lower bracket		2	55.00	-20.00 %	88.00
Front center grille base		1	381.80	-20.00 %	305.44
Front center grille outer garnish		1	385.00	-20.00 %	308.00
Front center grille Honda logo		1	68.50	-20.00 %	54.80
Front bumper		1	762.70	-20.00 %	610.16
Front bumper clips		10	5.00	-20.00 %	40.00
Front bumper side retainer		2	65.60	-20.00 %	104.96
Front bumper reinforcement		1	321.70	-20.00 %	257.36
Front support panel		1	576.20	-20.00 %	460.96
Front support panel top garnish		1	188.20	-20.00 %	150.56

Parts Subtotal 7,852.32

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Front number plate with casing		1.0	45.00	0.00 %	45.00

Materials Subtotal 45.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Check wiring	RnR	20.00	0.00 %	20.00
Tuff Coat	RnR	30.00	0.00 %	30.00
Panel beating	RnR	600.00	0.00 %	600.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Front fender	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	800.00	0.00 %	800.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 650.00

Paint Labor Subtotal 800.00

Labor Subtotal 1,450.00

Summary

Repair Cost 9,347.32

Discount(20 %) (1,869.46)

7,477.86

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 7,477.86