

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

Ergo
LKK
01/03/23

18/02/2023

Owner: GRAVITY CAR LEASING PTE LTD

Not withen
L1 Bmp @ 7450/h
Penning After Rain
5day

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SMZ5812A

1pc	front bonnet	892.10	B	\$ 1,125.00	✓
2pcs	front bonnet hinge @\$85.50		DIT	\$ 171.00	✓
1pc	front bonnet inner rubber		Pn	\$ 150.50	X
1pc	front bonnet inner lock	166.50	DIT	\$ 395.20	✓
1pc	front bonnet inner lock bracket		DIT	\$ 78.50	✓
2pcs	front headlamp @\$2580.50		My car	\$ 5,161.00	✓
2pcs	front headlamp chrome @\$185.50		nd	\$ 371.00	✓
2pcs	front headlamp top bracket @\$45.00		Pn	\$ 90.00	X
2pcs	front headlamp lower bracket @\$55.00		CM	\$ 110.00	✓
1pc	front centre grille base	381.80	CM	\$ 550.20	✓
1pc	front centre grille outer garnish	385	CM	\$ 420.50	✓
1pc	front centre grille "HONDA" logo		CM	\$ 68.50	✓
1pc	front bumper	762.70	B	\$ 951.70	✓
10pcs	front bumper clip @\$5.00		Mc	\$ 50.00	✓
2pcs	front bumper side retainer @\$65.60		DIT	\$ 131.20	✓
1pc	front bumper lower lid		Pn	\$ 450.30	X
1pc	front bumper lower grille		Pn	\$ 280.50	X
1pc	front bumper reinforcement	321.70	B	\$ 368.80	✓
2pcs	front fender @\$680.50		R	\$ 1,361.00	X
2pcs	front fender protector @\$285.50		Pn	\$ 571.00	X
1pc	front support panel	576.20	B	\$ 681.20	✓
1pc	front support panel top garnish	188.20	CM	\$ 385.20	✓
1pc	front air-con condensor		Pn	\$ 950.20	X
1pc	front radiator		Pn	\$ 1,150.20	X
				\$ 16,022.70	
	less 20%			\$ 3,204.54	
				\$ 12,818.16	
1set	front number plate & casing		nd	\$ 50.00	45sm
	wiring			\$ 100.00	2cl
	tuffkote			\$ 120.00	3cl
	spray painting			\$ 1,000.00	80cl
	labour charges			\$ 1,000.00	60cl
	Total			\$ 15,088.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

