

ASS. REC. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMX547J Yr Regn: 2018 / August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q7 c.c. 2995

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 63/422 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ4M7JD038363

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/35R22

R: 285/35R22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/02/23

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>1P SMRT.</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : _____

_____ S + RS. _____ SI

Photos

Others

Report Format: _____

Logic Sum / R.P.C

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0201/2023/EQ
DATE : 23-Feb-23
WIP : 64442

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/2/2023

YOUR INSURED VEH NO : SHD 6189 J

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4

Singapore 757705

Attn: Motor Claims Dept

OWNER'S NAME : MS KOH KUI MUI
ADDRESS : 17 YISHUN CLOSE
#10-35
SINGAPORE 768012
TELEPHONE : HP +65 94296937
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SI22V01421
VEHICLE NO : **SMX 547 J**
MODEL CODE : AUDI Q7 3.0 TFSI QU
MODEL YEAR : 2/8/2018
ENGINE NO : CRE 236477
CHASSIS NO : WAUZZZ4M7JD038363
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Feb-23
PLACE OF ACCIDENT : JUNCTION OF SELETAR WEST LINK AND SELETAR
AEROSPACE DR

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 547 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,300.00	900
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,000.00	2200 Super: 800 1800 Spacers: 900
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ Arc Trim: 200 x 2 = 400
TOTAL LABOUR CHARGES		\$ 4,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 547 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER / LOWER <i>Regis</i>	1	\$ 3,864.00	<i>P</i>
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 229.00	<i>+</i>
3	REAR BUMPER SPOILER <i>Delid</i>	1	\$ 1,492.00	<i>✓</i>
4	REAR BUMPER SPOILER LOWER TRIM <i>?</i>	1	\$ 126.00	<i>?</i>
5	REAR BOOT LID OPENING CONTROL UNIT <i>?</i>	1	\$ 440.00	<i>+</i>
6	REAR TAILGATE OPENING SENSOR LINE	1	\$ 230.00	<i>+</i>
7	REAR AERIAL KEY ACCESS	1	\$ 123.00	<i>+</i>
8	REAR AERIAL RETAINER	1	\$ 23.00	<i>+</i>
9	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,596.00	<i>+</i>
10	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>new</i>	2	\$ 34.00	<i>+</i>
11	REAR BUMPER HOLDING STRAP <i>?</i>	1	\$ 218.00	<i>?</i>
12	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 168.00	<i>+</i>
13	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 150.00	<i>+</i>
14	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	<i>+</i>
15	REAR PARKING AID SEAL RING	4	\$ 11.00	<i>+</i>
16	REAR WHEEL COVER - LH / RH <i>new</i>	2	\$ 962.00	<i>✓</i>
17	EXHAUST TAIL PIPE TRIM - LH / RH <i>new</i>	2	\$ 730.00	<i>+</i>
18	REAR BUMPER TAIL LIGHT - LH / RH	2	\$ 854.00	<i>+</i>
19	SUNDRIES <i>?</i>		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 12,193.00	
TOTAL LABOUR CHARGES		:	\$ 4,852.00	
GRAND TOTAL		:	\$ 17,045.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *28/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

 ALLAN WU
CLAIMS CONSULTANT