

ASS. REC. BY:

REF:

FC2/230019P8/kny3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

04-53 Carros

329A

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$56K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SM14 7122P

Yr Regn:

11, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV

c.c

1498

Colour

M.D. Gray

A/C:

Insured / Std / Nil / NA

Sp. Reading

77947

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

JHMRU1810GX 201291

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

4

mm

L/Bal.

4

mm


D.O.A.

19/2/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

16/6 11:30 AM @ 3000L Carros (Red. \$ 9792.80, 7670)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) \$ - RS. SI

) Fuel

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

| Adjustment of Spare Parts Costs for Repairs SMH 7122P |       |                                          |    |                |          |          |
|-------------------------------------------------------|-------|------------------------------------------|----|----------------|----------|----------|
| Item                                                  | Qty   | Vehicle parts description                |    | \$             |          |          |
| 1                                                     | 1     | rear bumper 492                          | Bu | 790.00         | ✓        |          |
| 2                                                     | 2     | Rear bumper side retainer                | su | 100.00         | X        |          |
| 3                                                     | 1 set | Rear bumper fasteners                    | su | 45.00          | —        |          |
| 4                                                     | 2     | Rear bumper reflector LH & RH            | su | 360.00         | X        |          |
| 5                                                     | 1     | rear side bumper cover LH                | su | 380.00         | X        |          |
|                                                       | 2     | rear fender inner trim board             | su | 1350.00        | X        |          |
|                                                       | 2 set | rear fender inner trim board fasteners   | su | 80.00          | X        |          |
| 6                                                     | 1     | Tailgate                                 | su | 900.00         | ✓        |          |
| 7                                                     | 1     | Tailgate Honda emblem                    | su | 75.00          | X        |          |
| 8                                                     | 1     | Tailgate <sup>148V</sup> vezel emblem 32 | su | 75.00          | —        |          |
| 9                                                     | 1     | Tailgate weatherstrip 7920               | su | 255.00         | 508 su   |          |
| 10                                                    | 1 set | Tailgate inner trim fasteners            | su | 50.00          | X        |          |
| 11                                                    | 1     | Tailgate inner board                     | su | 380.00         | X        |          |
| 12                                                    | 2     | Tailgate lamp LH & RH                    | su | 1850.00        | X        | e 461.00 |
| 13                                                    | 2     | Tailgate number plate lamp               | su | 130.00         | X        |          |
| 14                                                    | 1     | Rear windscreen wiper                    | su | 65.00          | X        |          |
| 16                                                    | 1     | Rear end panel                           | su | 495.00         | X        |          |
| 17                                                    | 1     | Rear end panel top garnish               | su | 220.00         | 180.90   |          |
| 18                                                    | 1 set | Rear end panel top garnish fasteners     | su | 45.50          | X        |          |
| 19                                                    | 1     | Windscreen moulding 121.60               | su | 188.00         | —        |          |
| 22                                                    | 2     | bootlid rubber stopper                   | su | 35.00          | X        |          |
| 25                                                    | 2     | Wheel arch LH & RH                       | su | 520.00         | X        |          |
|                                                       | 1     | spare tyre panel                         | su | 700.00         | X        |          |
|                                                       | 1     | spare tyre panel board assy              | su | 420.00         | X        |          |
|                                                       | 2     | taillamp LH & RH                         | su | 1980.00        | e 429.90 |          |
|                                                       | 1     | tailgate chrome moulding garnish         | su | 280.00         | X        |          |
| 26                                                    | 1     | Tailgate lock 189.40                     | su | 260.00         | ✓        |          |
|                                                       |       |                                          |    | 12028.50       |          |          |
| Less 20%                                              |       |                                          |    | 2405.7         |          |          |
|                                                       |       |                                          |    | <b>9622.80</b> |          |          |

| Special nett item  |   |                            |    |               |        |  |
|--------------------|---|----------------------------|----|---------------|--------|--|
| 1                  | 1 | Rear number plate w casing | su | 60.00         | X      |  |
| 2                  | 1 | Rear windscreen sealant    | su | 60.00         | 4 ofal |  |
| 3                  | 1 | End panel sealant          | su | 60.00         | X      |  |
| 4                  | 1 | Rear camera                | su | 350.00        | X      |  |
| 5                  | 1 | Reverse sensor             | su | 320.00        | X      |  |
| <b>Total parts</b> |   |                            |    | <b>850.00</b> |        |  |

Carry out body cavity preservation 90.00 301

To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat 800.00 5002

Not Noted  
1/1/2020 @ 3000h  
Recovery After Paint  
4 days

to respray and putty damage parts

800.00 600l

Remove & refix rear windscreen

150.00 120l

Check wiring

80.00 20l

Remove & refix reverse sensor

100.00 50l

Remove & refix rear camera

nm 100.00 X

Remove & refix tailgate components

100.00 60l

Remove & reinstall rear boot upholstery

100.00 50l

**Total labour**

**2320.00**

12790.8

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: