




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO23001999/Kwy3m4 Date: 03/03/2023 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SMJ 1448D	Veh. Inspected	SML 84R
Policy No.	D22MTPV01003324	Coverage (\$)	0.00
Claim No.	CMTD2300743/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	22/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTEKB3GH50J004342	Colour	METALLIC DARK BLUE
Odometer	68402 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/50 R19	MICHELIN	8 mm
L/H Front Tyre	255/50 R19	MICHELIN	8 mm
R/H Rear Tyre	255/50 R19	MICHELIN	8 mm
L/H Rear Tyre	255/50 R19	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5. General Information			
Accident Date	18/02/2023	Inspect Date / Time	27/02/2023 ( 01:55 PM )
Survey held at	BAK HENG MOTOR REPAIRING CO. BLOCK 5032 ANG MO KIO INDUSTRIAL PARK II, #01-291 SINGAPORE 569535		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/SMO23001999/Kwy3m4

## Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.