

Success United Pte Ltd (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
VIJAYAGANESH NADARAJA

Ezlyna

Singapore

Claimant Insurer: Singapore Life Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/23-041
Policy No:		Date of Loss:	18/02/2023
Vehicle Reg. No.:	SMD6346M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	JESSICA YEOH GEK LI		
Make/Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Vehicle Reg. Date:	29/08/2018
Vehicle Colour:	GREY	Chassis No:	MHFZ28H3200055584
Engine No:	2NRX346575		
Odometer:	67212 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO POLICE REPORT. REPORT NO: T/20230218/2100		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	1,849.50
Miscellaneous Items	0.00
Labour	1,080.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (\$\$)	3,729.50
+ GST 8.00% (\$\$)	298.36
Nett Amount (\$\$)	4,027.86

This claim is handled by: TAN WEI NI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2023)	
Parts: M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	Success United Pte Ltd/SMD6346M/21/02/2023 16:24	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear tail gate <i>Revised</i>	0.00	0.00	✓ *480.00 F
2	1		*Rear tail gate weatherstrip <i>new</i>	0.00	0.00	✗ *150.00 F
3	1		*Rear tailgate mechanism lock <i>new</i>	0.00	0.00	✗ *185.00 F
4	1		*Rear tailgate damper LH <i>new</i>	0.00	0.00	✗ *130.00 F
5	1		*Rear Sienta emblem <i>new</i>	0.00	0.00	✓ *38.00 F
6	1		*Rear lower bumper <i>Revised</i>	0.00	0.00	✓ *240.00 F
7	1		*Rear bumper side holder LH <i>new</i>	0.00	0.00	✗ *42.00 F
8	1		*Rear corner bumper LH <i>Revised</i> <i>Revised</i>	0.00	0.00	✗ *85.00 F
9	1		*Rear bumper guard garnish LH <i>Revised</i>	0.00	0.00	✓ *55.00 F
10	3		*Rear windscreen moulding <i>new</i>	0.00	0.00	✓ *90.00 F
11	1		*Rear windscreen sealant <i>new</i>	0	0.00	✓ *40.00 FS
12	1		*Rear boot lamp LH <i>new</i>	0.00	0.00	✗ *150.00 F

F=Franchise part, S=SpcNett.

988			Sub Total (S\$)	1,685.00
+ 10% 1086.80			+ Margin on L,N Items 10.00% (S\$)	164.50
5 N: 40			Total Parts (S\$)	1,849.50

Success United Pte Ltd/SMD6346M/21/02/2023 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To putty and respray painting on boot lid, bumper and corner bumper LH.	New	400 800.00
<u>Labour Items</u>			
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & whereconsistent to the accident.	New	400 800.00
3	To remove, rearrange electrical wirings, check lighting.	New	30 80.00
4	Labour to remove, replace rear windscreen.	New	120 200.00
Gross Labour Cost (\$\$)			1,880.00

Success United Pte Ltd/SMD6346M/21/02/2023 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian G

L/S 24/02/23.

04 Days

total: 2076.80

L/S: 1650 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: