

**Section A - Accident Details**

|                                    |                                 |
|------------------------------------|---------------------------------|
| Registration Number                | SHB1289Y                        |
| Case Reference Number              | TAX/02/23/2050                  |
| Registration Date                  | 1/Oct/2021                      |
| Company Type                       | Strides Taxi Pte Ltd            |
| Make                               | MORRISGARAGES                   |
| Model                              | MG5                             |
| Name of Driver                     | YEOH SIANG BIN                  |
| Type of Accident                   | Head to Rear                    |
| Accident Date and Time             | 21/Feb/2023 3:28 PM             |
| Accident Reported Date and Time    | 21/Feb/2023 4:49 PM             |
| Is Surveyor Required?              | Yes                             |
| Survey by                          |                                 |
| Vehicle is Towed Back?             | No                              |
| Towed Back Date and Time           |                                 |
| Replacement Vehicle issued?        | No                              |
| Job Card Number                    | 24117691                        |
| Special Instruction to ARC, if any | DAMAGE TO THE REAR OF TAXI (TP) |
| Prepared Date and Time             | 21/Feb/2023 6:19 PM             |
| Chassis Number                     |                                 |
| Mileage                            |                                 |
| Work Shop                          |                                 |
| Repair Completion Date and Time    |                                 |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                                                                                                    |
|------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                                                                                                |
| Total Labour Cost            | \$1,800.00                                                                          | \$800.00                                                                                                                                                           |
| Total Spray Cost             | \$2,172.00                                                                          | \$620.00                                                                                                                                                           |
| Total Spare Part Cost        | \$11,132.89                                                                         | \$5,029.77                                                                                                                                                         |
| Total Other Cost             | \$2,410.00                                                                          | \$700.00                                                                                                                                                           |
| <b>TOTAL COST</b>            | <b>\$17,514.89</b>                                                                  | <b>\$7,149.77 (P/P)</b>                                                                                                                                            |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                       | <b>\$0.00</b>                                                                                                                                                      |
| Number of Repair Days        | 11.0                                                                                | 6.0                                                                                                                                                                |
| Prepared / Adjusted By       | <b>Boon Chew Tay</b>                                                                | <b>Kenneth Kong (LKK) / AIG</b>                                                                                                                                    |
| ARC / Surveyor Sign Off Date | <b>01/03/2023 12:19 PM</b>                                                          | <b>01/03/2023 9:26 AM</b>                                                                                                                                          |
| Signature                    |  |                                                                                 |
| Remarks                      | INITIAL 8DAYS / SUPP 2DAYS / SUPP 2.0 1DAY / TOTAL 11 DAYS                          | PART BY PART REPAIR / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com |

**Section C - Quotation and Accident Invoice Details**

|                         |              |                       |  |
|-------------------------|--------------|-----------------------|--|
| <b>Quotation Number</b> | QN-2303-0225 | <b>Invoice Number</b> |  |
| <b>Quotation Date</b>   | 17.03.2023   | <b>Invoice Date</b>   |  |
| <b>Invoice Amount</b>   |              | <b>Prepared Date</b>  |  |

**Section D - Details of Repair Estimates**

| <b>Part 1 - Labour Works</b> |                          |                                            |
|------------------------------|--------------------------|--------------------------------------------|
| <b>Job Scope</b>             | <b>Quotation from AR</b> | <b>Adjusted by Surveyor, if applicable</b> |
| TO REPAIR REAR PORTION       | \$1,800.00               | \$800.00 ✓                                 |
| <b>Total Labour</b>          | <b>\$1,800.00</b>        | <b>\$800.00</b>                            |

| <b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b> |                           |                                            |
|------------------------------------------------------------------|---------------------------|--------------------------------------------|
| <b>Job Scope</b>                                                 | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
| TO RESPRAY REAR BUMPER                                           | \$428.00                  | \$220.00 ✓                                 |
| TO RESPRAY REAR PANEL                                            | \$230.00                  | \$0.00                                     |
| TO RESPRAY TAIL GATE                                             | \$428.00                  | \$220.00 ✓                                 |
| TO RESPRAY REAR FENDER LH                                        | \$428.00                  | \$0.00                                     |
| TO RESPRAY REAR FENDER RH                                        | \$428.00                  | \$0.00                                     |
| TO RESPRAY REAR PANEL                                            | \$230.00                  | \$180.00 ✓                                 |
| <b>Total Spray Painting &amp; Panel Beating</b>                  | <b>\$2,172.00</b>         | <b>\$620.00</b>                            |

| <b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b> |                           |                                            |
|----------------------------------------------------------------------------|---------------------------|--------------------------------------------|
| <b>Job Scope</b>                                                           | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                          | \$350.00                  | \$150.00 ✓                                 |
| TO REMOVE AND REFIX REAR WINDSCREEN                                        | \$120.00                  | \$120.00 ✓                                 |
| TO CHECK & RESET SYSTEM FUNCTION                                           | \$350.00                  | \$0.00                                     |
| TO WASH AND VACUUM                                                         | \$60.00                   | \$0.00                                     |
| TO CHECK WIRING AND SYSTEM FUNCTION                                        | \$120.00                  | \$20.00 ✓                                  |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                    | \$100.00                  | \$30.00 ✓                                  |
| TO REMOVE AND REFIX REAR WINDSCREEN                                        | \$120.00                  | \$120.00 ✓                                 |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                          | \$350.00                  | \$0.00                                     |
| TO TRANSFER REAR TAILGATE MECHANISM                                        | \$120.00                  | \$60.00 ✓                                  |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                                    | \$120.00                  | \$50.00 ✓                                  |
| TO REPLACE SUNDRY PARTS                                                    | \$100.00                  | \$0.00                                     |
| TO CHECK & RESET SYSTEM FUNCTION                                           | \$350.00                  | \$0.00                                     |
| ISOLATED OF (EV) (NET)                                                     | \$150.00                  | \$150.00 ✓                                 |
| <b>Total Other Costs</b>                                                   | <b>\$2,410.00</b>         | <b>\$700.00</b>                            |

| <b>Part 4 - Spare Parts / Material Usage</b> |                |                     |                       |                 |                        |                     |                         |                           |                          |
|----------------------------------------------|----------------|---------------------|-----------------------|-----------------|------------------------|---------------------|-------------------------|---------------------------|--------------------------|
| <b>Part Number</b>                           | <b>Portion</b> | <b>Stock Number</b> | <b>Part Name</b>      | <b>Quantity</b> | <b>List Price (\$)</b> | <b>Discount (%)</b> | <b>Final Price (\$)</b> | <b>Estimator Approved</b> | <b>Surveyor Approved</b> |
|                                              |                | 10328219-SEPP       | TAIL GATE ASM-LIFT    | 1.00            | \$1,928.26             | 10.00               | \$1,735.43              | Replace                   | Replace                  |
|                                              |                | 10103179            | HINGE ASM-L/GATE - LH | 1.00            | \$30.89                | 100.00              | \$0.00                  | Replace                   | Repair                   |

✓ BT  
R

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 24/03/2023

User ID : PohSuan

|  |  |               |                                              |      |            |        |          |         |           |         |
|--|--|---------------|----------------------------------------------|------|------------|--------|----------|---------|-----------|---------|
|  |  | 10103178      | HINGE ASM-L/GATE - RH                        | 1.00 | \$30.89    | 100.00 | \$0.00   | Replace | Repair    | R       |
|  |  | 10444797      | STRUT ASM-L/GATE - LH                        | 0.00 | \$52.52    | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10444798      | STRUT ASM-L/GATE -RH                         | 0.00 | \$52.52    | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10321485      | WEATHERSTRIP-L/GATE                          | 0.00 | \$73.53    | 0.00   | \$0.00   | Replace | Not Given | X XSVC  |
|  |  | 10314527      | LATCH ASM-L/GATE                             | 0.00 | \$139.36   | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10022051      | SWITCH-L/GATE OPEN                           | 0.00 | \$30.68    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10395721-SEPP | PANEL ASM-RR END                             | 1.00 | \$708.66   | 100.00 | \$0.00   | Replace | Repair    | R       |
|  |  | 10562676      | PLATE ASM-RR LIC PLT                         | 1.00 | \$96.40    | 10.00  | \$86.76  | Replace | Replace   | √ NEC   |
|  |  | 10935050      | EMBLEM ASM-RR LIC PLT ( MG )                 | 1.00 | \$62.92    | 10.00  | \$56.63  | Replace | Replace   | √ NEC   |
|  |  | 10885560      | EMBLEM ASM-L/GATE ( MG5 SW)                  | 1.00 | \$21.84    | 10.00  | \$19.66  | Replace | Replace   | √ NEC   |
|  |  | 10896035      | EMBLEM ASM-L/GATE (SW EV )                   | 1.00 | \$33.90    | 10.00  | \$30.51  | Replace | Replace   | √ NEC   |
|  |  |               | STRIDES LOGO                                 | 1.00 | \$7.80     | 0.00   | \$7.80   | Replace | Replace   | √ NEC   |
|  |  |               | STICKER DECAL 6555 8888                      | 1.00 | \$21.60    | 0.00   | \$21.60  | Replace | Replace   | √ NEC   |
|  |  |               | NUMBER PLATE                                 | 0.00 | \$35.00    | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  |               | NUMBER PLATE FRAME                           | 0.00 | \$25.00    | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10369261-SPRP | FASCIA-RR BPR                                | 1.00 | \$758.48   | 10.00  | \$682.63 | Replace | Replace   | √ BUC   |
|  |  | 10751490      | FASCIA-RR BPR LWR                            | 1.00 | \$230.68   | 10.00  | \$207.61 | Replace | Replace   | √ DD    |
|  |  | 10359003      | FINISHER-RR BPR - RH                         | 1.00 | \$47.42    | 10.00  | \$42.68  | Replace | Replace   | √ CUT   |
|  |  | 10359002      | FINISHER-RR BPR - LH                         | 0.00 | \$47.42    | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10465727      | BRACKET ASM-RR BPR FASCIA SI-RH              | 0.00 | \$29.85    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10465723      | BRACKET ASM-RR BPR FASCIA SI                 | 0.00 | \$29.85    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10326371      | BRACKET-RR BPR FASCIA SI MTG - RH            | 0.00 | \$46.08    | 0.00   | \$0.00   | Replace | Check     | X X SVC |
|  |  | 10326369      | BRACKET-RR BPR FASCIA SI MTG - LH            | 0.00 | \$46.08    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10371766      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 0.00 | \$13.20    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10371768      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 0.00 | \$12.90    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10371790      | BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST | 0.00 | \$12.90    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10449056      | BRACKET-RR BPR FASCIA LWR MTG - RH           | 0.00 | \$12.80    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10449047      | BRACKET-RR BPR FASCIA LWR MTG - LH           | 0.00 | \$12.80    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 90003417      | SCRIVET-RR BPR FASCIA                        | 0.00 | \$0.84     | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10327894      | BAR ASM-RR BPR IMP                           | 0.00 | \$339.77   | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10964627      | WINDOW ASM-REAR (WINDSCREEN REAR)            | 0.00 | \$323.44   | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  |               | SEALANT SIKAFLEX                             | 0.00 | \$37.00    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10587409      | LAMP ASM-TAIL(BODY SI) - LH                  | 0.00 | \$764.09   | 0.00   | \$0.00   | Replace | Not Given | X       |
|  |  | 10587410      | LAMP ASM-TAIL(BODY SI) - RH                  | 1.00 | \$764.09   | 10.00  | \$687.68 | Replace | Replace   | √ CRA   |
|  |  | 10587411      | LAMP ASM-TAIL(LID SI) - LH                   | 1.00 | \$407.68   | 10.00  | \$366.91 | Replace | Replace   | √ CRA   |
|  |  | 10587412      | LAMP ASM-TAIL(LID SI) - RH                   | 1.00 | \$407.68   | 10.00  | \$366.91 | Replace | Replace   | √ CRA   |
|  |  | 10726677      | LAMP ASM-RR FOG - RH                         | 1.00 | \$189.07   | 10.00  | \$170.16 | Replace | Replace   | √ CRA   |
|  |  | 10726676      | LAMP ASM-RR FOG - LH                         | 0.00 | \$36.30    | 0.00   | \$0.00   | Replace | Not Given | X SVC   |
|  |  | 10376550-WSD  | SENSOR-RR PARK DIST CONT                     | 0.00 | \$65.00    | 0.00   | \$0.00   | Replace | Check     | X       |
|  |  | 10345435-SEPP | PANEL-BODY SI OTR-L                          | 1.00 | \$1,747.82 | 100.00 | \$0.00   | Replace | Repair    | R       |
|  |  |               | STICKER ELECTRIC ( LOGO                      | 1.00 | \$21.60    | 0.00   | \$21.60  | Replace | Replace   | √ NEC   |

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 24/03/2023

User ID : PohSuan

|              |  |               |                         |      |                    |        |                   |         |         |       |
|--------------|--|---------------|-------------------------|------|--------------------|--------|-------------------|---------|---------|-------|
|              |  | 10720690-SEPP | PANEL-BODY SI OTR - RH  | 1.00 | \$1,434.89         | 100.00 | \$0.00            | Replace | Repair  | R     |
|              |  |               | STICKER ELECTRIC ( LOGO | 1.00 | \$21.60            | 0.00   | \$21.60           | Replace | Replace | √ NEC |
| <b>Total</b> |  |               |                         |      | <b>\$11,213.10</b> |        | <b>\$4,526.17</b> |         |         |       |

| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |                                   |          |               |              |                  |           |                |
|--------------------------------------------------------------|---------|--------------|-----------------------------------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number                                                  | Portion | Stock Number | Part Name                         | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|                                                              |         | 10964627     | WINDOW ASM-REAR (WINDSCREEN REAR) | 1.00     | \$323.44      | 10.00        | \$291.10         | Replace   | Replace        |
|                                                              |         | 10327894     | BAR ASM-RR BPR IMP                | 1.00     | \$339.77      | 100.00       | \$0.00           | Replace   | Repair         |
|                                                              |         | 10376550-WSD | SENSOR-RR PARK DIST CONT          | 3.00     | \$65.00       | 10.00        | \$175.50         | Replace   | Replace        |
|                                                              |         |              | SEALANT W/SCREEN                  | 1.00     | \$37.00       | 0.00         | \$37.00          | Replace   | Replace        |
|                                                              |         |              | NUMBER PLATE                      | 0.00     | \$35.00       | 0.00         | \$0.00           | Replace   | Not Given      |
|                                                              |         |              | NUMBER PLATE FRAME                | 0.00     | \$25.00       | 0.00         | \$0.00           | Replace   | Not Given      |
| Total                                                        |         |              |                                   |          | 825.21        |              | 503.60           |           |                |

5,029.77  
+ 800.00  
+ 1320.00  
7,149.77