

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Feb 28 2023
	Ticket No: LKK-J000025	Vehicle No: SLJ4204H
	Policy No: SD22V07707/VTN/R00	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Tan Wei Auto Pte Ltd Vehicle: TOYOTA HARRIER 2 Premium Advance 2016 Kilometer: 75419 Color: WHITE Fuel: PETROL PH: +65 86865535 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	FRONT BUMPER	Part	1.00	962.00	529.10	432.90	529.10	529.10
2	BUMPER CLIPS	Part	1.00	50.00	50.00	0.00	50.00	50.00
3	FRONT R/H RIM	Part	1.00	750.00	750.00	0.00	750.00	750.00
							Taxable Value	1,329.10
							Discount Total	432.90
							Grand Total	1,329.10

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
4	LABOUR FOR CHECKING ON WIRING	Labour	-	20.00	20.00	0.00	20.00	20.00
5	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING CUTTING OFF, WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE OF FRONT BUMPER, FRONT R/H FENDER, FRONT R/H DOOR	Labour	-	380.00	380.00	0.00	380.00	380.00
6	SPRAYPAINTING & PUTTY OF FRONT BUMPER, FRONT R/H FENDER, FRONT R/H DOOR	Labour	-	600.00	270.90	329.10	270.90	270.90
							Taxable Value	670.90
							Discount Total	329.10
							Grand Total	670.90

					Parts Total	1,329.10
					Labour Total	670.90
					GST Total	0.00
					Grand Total	2,000.00
					Balance	2,000.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature