

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh Zan Wei

Date: 24 Feb 2023

**Preliminary Advice**

Vehicle No	: SMT9387R	Accident Date	: 21/02/2023
Make	: HONDA FIT	Policy No.	: MP321564
Assignment Date	: 23/02/2023	Excess	: S\$300.00
Date of Inspection	: 23/2/2023	Est. Duration of Repair	: 5
Inspection At	: CHARN'S CUSTOMCRAFT		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,879.00
Revised Amount	:S\$	1,913.00
Check Items (Estimated)	:S\$	726.00
Total	:S\$	2,639.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	29,070.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,930.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair.

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .