Charn's Customcraft (Co.Reg.No:25151300M)

Block 1010 Bukit Merah Lane 3, #01-105

Singapore 159724

Tel: 62717054 Fax: 62736676 Email: charns@singnet.com.sg

INSURER:

Present Location:

**HL Assurance Pte Ltd (HQ)** 

CHARN'S CUSTOMCRAFT (HQ)

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	ARTHUR ATTENDED
Policy No:	MP321564	Date of Loss:	21/02/2023
Vehicle Reg. No.:	SMT9387R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NEO LEE HONG	Contact No:	+6596773834
Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	24/07/2020
Vehicle Colour:	Grey	a see announced to the Contract of the Contrac	
Engine No:	L13B3944640	Chassis No:	GK33430185
Odometer:	28928 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day	7		

	+ GST 8.00% (S\$)	230.32
	Gross Total (S\$)	2,879.00
Townig		0.00
Towing	经济等加强的风味的证据。	0.00
Paintwork Labour	D. Carlotter and C. Car	1,720.00
Labour	等 <b>的</b> 特别是对自己的。可以是我们的自己的。	180.00
Parts Miscellaneous Items		979.00
COST OF CLAIMS		Amount

This claim is handled by: SHARON LEE CHIA LING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Feb 2023)

Parts: 143 HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)
Print Code: Charn's Customcraft/SMT9387R/22/02/2023 17:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Estimates on Parts**

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*Front kunckle RHS *	0.00	0.00	*200.00 F
2	1	*Front kunckle bearing RHS	0.00	0.00	*120.00 F
3	1	*Front shock absorber RHS 7.	0.00	0.00	*200.00 F
4	11 Townson	*Front lower arm RHS	0.00	0.00	*140.00 F
5	1	*Front rim RHS	0.00	0.00	*150.00 F
6	1 Interest	*Front hub cap RHS M ()	0.00	0.00	*80.00 F
F=Fra	anchise part.	E		THE RESERVE AND	and the state of t
		Sub Total (S\$)			890.00
		+ Margin on L,N Items 10.00% (S\$)			89.00
		Total Parts (S\$)			979.00

Charn's Customcraft/SMT9387R/22/02/2023 17:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Qty Particulars

Amount Miscellaneous Items

Front tyre RHS (S/NETT) 1.00 1

180.00

Sub Total (S\$)

180.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Lat	pour Items		
1	Alignment	New	60.00
2	Remove and replace front u/carriage RHS	New ()	188.00
3	Jacking, panel beating, repair and straighten front bumper, front fender RHS, RHS side mirror cover, front door RHS, rear door RHS, rear fender RHS and rear bumper.	New 30	` ' /
4	Putty and respray front bumper, front fender RHS, RHS side mirror cover, front door RHS, rear door RHS, rear fender RHS and rear bumper.	New / vv	U 1,100.00

Gross Labour Cost (S\$)

Charn's Customcraft/SMT9387R/22/02/2023 17:06. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ap 90010068 5 #days

23/02/23 @1520

EXCESS: 300

Revery

Resurry before report

Regularl alignat copy