

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7241J

Make : HYUNDAI

Model : IONIQ(G2)

Date: 14/02/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER <i>scr</i>			\$ 481.10
10	FRT BUMPER CLIPS <i>XNN</i>			\$ 22.00
1	FRT BUMPER UPPER CENTRE MOULDING <i>scr</i>			\$ 368.50
1	FRT BUMPER SIDE BRACKET LH <i>? XNN</i>			\$ 28.00
1	HEADLAMP LH <i>scr</i>			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH <i>? XNN</i>			\$ 93.60
1	DAY LIGHT RH <i>? XNN</i>			\$ 642.50
	SUB TOTAL			\$ 3,746.00 <i>2959.90</i>
	LESS 20%			\$ 749.20 <i>591.98</i>
	DISCOUNTED TOTAL			\$ 2,996.80
				\$ -
				nett
	Labour Charge			
	PANEL BEATING		\$ 400.00	<i>350</i>
	SPRAY PAINTING CHARGE		\$ 300.00	<i>250</i>
	CHECK ALL LIGHTING		\$ 60.00	<i>30</i>
	TOTAL LABOUR		\$ 760.00	
	ESTIMATE TOTAL		\$ 3,756.80 <i>2997.92</i>	
				<i>20% = 599.58</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

T = *1398.33*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 days *~2400\$*
L/S
15/2/23
1st time *430pm*