

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 24 Feb 2023

**Preliminary Advice**

Vehicle No	: SMT5280R	Accident Date	: 19/02/2023
Make	: BMW 118I	Policy No.	: DMPG22007271
Assignment Date	: 23/02/2023	Excess	: S\$0.00
Date of Inspection	: 23/2/2023	Est. Duration of Repair	: 3
Inspection At	: PERFORMANCE MOTORS LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,581.25
Revised Amount	:S\$	4,885.20
Check Items (Estimated)	:S\$	7,965.05
Total	:S\$	12,850.25

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	50,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	79,006.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .