

# Performance Motors

BMW Dealer



## Supplementary

Estimate No. : b1 65092  
Date Estimated : 21/02/2023  
Prepared By : Yap Mee Key

Page No. :

**- ESTIMATE REPAIR FOR -**

Ho Ying Ci  
263 River Valley Road  
#10-21

Singapore 238309

**- ACCOUNT - 136**

Ergo Insurance Pte Ltd  
8 Temasek Boulevard  
#04-01 Suntec Tower 3  
Singapore 038988

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMT5280R	WBA7K320107F86478	26/06/2020	118i	29437

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
** To replace front bumper and attachments, top air duct, front grille, front RH moulding, bottom carrier, grate centre closed, RH grid lateral, RH trim side grille include carrying out necessary repairs caused by the accident	1,275.00	0.00	1,275.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SUPPORT NUMBER PLATE ECE cracked	76.75	1.00	0.00	76.75
# PLAQUE 82MM nec	72.85	1.00	0.00	72.85

**# SUPPLEMENTARY ITEMS**

Total Labour :	1,275.00
Total Parts :	149.60
Total Labour & Parts (before GST) :	1,424.60

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W



A Sime Darby Motors Company