

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Allianz.

Hui Rong

Page No. 1

Vehicle No. SMP4652D

HONDA SHUTTLE

GK82100218

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR NUMBER PLATE LAMP @\$77 <i>new</i>		154.00	+
2	REAR BUMPER <i>del</i>		993.30	✓
3	REAR BUMPER SIDE HOLDER @30.40 <i>new</i>		60.80	+
4	REAR BUMPER REFLECTOR @68.30 <i>attached</i>		136.60 68.30	+
5	REAR BUMPER SIDE SPONGE @60.20 <i>cracked</i>		120.40	✓
6	REAR BUMPER TOP CHROME MOULDING <i>scratched</i>		109.40	✓
7	REAR END PANEL <i>dent</i>		615.40	✓
8	REAR END PANEL TOP GARNISH <i>del</i>		248.70	✓
9	REAR END PANEL SIDE EXTENSION @150.40 <i>Repis</i>		300.80	+
10	REAR END PANEL BUZZER <i>green</i>		80.90	+
11	REAR END PANEL ANTENNA SENSOR		108.90	+
12	TAILLAMP @520.80 <i>cracked</i>		1041.60	✓
13	TAILGATE <i>dent</i>		1193.40	✓
14	TAILGATE LOCK <i>dent</i>		265.20	✓
15	TAILGATE WEATHERSTRIPE <i>at</i>		185.40	✓
16	TAILGATE INNER TRIM BOARD <i>cracked</i>		398.40	✓
17	TAILGATE DAMPER @242.10 <i>new</i>		484.20	+
18	TAILGATE REFLECTOR @385.90 <i>new</i>		771.80	+
19	TAILGATE OUTER GARNISH <i>new</i>		363.30	+
20	TAILGATE GLASS MOULDING <i>new</i>		140.90	+
21	HONDA LOGO <i>new</i>		45.90	+
22	SHUTTLE WORDING <i>new</i>		50.60	✓
23	REAR FENDER INNER TRIM @337.40 <i>new</i>		674.80	+
24	SPARE TYRE PANEL <i>Repis</i>		1185.90	+
25	SPARE TYRE PANEL TOP COVER <i>new</i>		528.20	+
26	TOOLS TRAY <i>new</i>		321.90	+
27	TOOLS TRAY JACK COVER <i>new</i>		100.90	+
28	UTILITY TRAY SPONGE <i>new</i>		298.40	+
29	REAR EXHAUST PIPE		688.20	+
30	REAR EXHAUST PIPE MOUNTING <i>new</i>		35.90	+
31	REAR EXHAUST PIPE GASKET <i>new</i>		34.10	+
32	REAR EXHAUST PIPE HEAT SHIELD		145.60	+
			11883.80	
		less 20%	2376.76	20%
			9507.04	
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE <i>green</i>		30.00	+
2	REAR NUMBER PLATE HOLDER <i>new</i>		30.00	+
3	REAR BUMPER CLIPS <i>new</i>		50.00 30.00	+
4	REVERSE SENSOR <i>del</i>		280.00 20.00	✓
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		20.00	✓
6	REAR END PANEL SEALANT <i>new</i>		60.00	✓
7	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>		50.00 30.00	+
8	TAILGATE OUTER GARNISH CLIPS <i>new</i>		30.00	+
9	TAILGATE GLASS SEALANT <i>new</i>		60.00	+
10	REAR CAMERA <i>new</i>		480.00	+
11	REAR FENDER INNER TRIM CLIPS <i>new</i>		60.00	+

5431

4344.80

400

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. SMP4652D

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1500.00	800
2	SPRAY PAINTING	1400.00	800
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	60
5	TO REMOVE UPHOLSTERY	150.00	60
6	TO TRANSFER TAILGATE FITTINGS	150.00	60
7	TO REMOVE TAILGATE GLASS	180.00	120
8	TO REMOVE REVERSE SENSOR	100.00	50
9	TO REMOVE REAR CAMERA	100.00	50
10	TO REMOVE REAR VIDEO RECORDER	100.00	50
11	TO REMOVE REAR EXHAUST PIPE	150.00	x
	Labour Total :	4080.00	
	TOTAL (PARTS & LABOUR):	14737.04	

2080

total: 682480
L/S: 54K.
06 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: