

REPAIR ESTIMATE

LKK-

DATE: 13.02.2023INSURANCE: INCOME (US)MODEL: Hyundai i40MVA: LIMITSVEHICLE NO.: SHC7229B

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper Br ✓	1		\$ 1,052.20
	Front Bumper Clips me ✓	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Brkt LH Br ✓	1		\$ 22.40
	Front Wheel Cap LH Scr ✓	1		\$ 217.20
	Front Fender LH Bve ✓	1		\$ 663.00
	Front Fender Shield LH ?	1		\$ 174.90 LNN
Scr	HeadLamp LH Br ✓	1		\$ 1,388.00
	Bonnet Denaf Scr (R)	1		\$ 2,508.80 R
	Wing Mirror LH Br ✓	1		\$ 670.00
	Front Door LH Scr (R)	1		\$ 2,707.70 R
	SUB TOTAL			\$ 9,426.20 4034.80
	LESS 20%			\$ 1,885.24 806.96
	DISCOUNTED TOTAL			\$ 7,540.96 3227.84
	Front Door ComfortDelGro LH me ✓	1		\$ 75.00 ✓
	LESS 10%			\$ 7.50
	S/NETT TOTAL			\$ 67.50
	SPARE PARTS TOTAL			\$ 7,608.46
	Labour Charge			
	Panel Beating			\$ 900.00 840
	Spray Painting Charge			\$ 1,200.00 1100
	Check Lightings			\$ 40.00 ✓
	Tuff Kote			\$ 40.00 ✓
	Wheel Alignment			\$ 120.00 LNN
	Towing Fee			\$ 60.00 X
	TOTAL LABOUR			\$ 2,360.00
	ESTIMATE TOTAL			\$ 9,968.46 5315.34
				20% = 1067.06

LKK Auto Consultants hence notify the Repairer of the following:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 days
4/5
13/2/23
SPM
T = 4252.27
1 rfm 4250
M