



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 1993T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	495.60	495.60
2	REAR BUMPER SIDE HOLDER -LH & RH	NECESSARY	70.20	70.20
2	REAR BUMPER REFLECTOR-LH & RH	NOT NECESSARY	145.00	-
1	REAR BUMPER LOWER GARNISH	DEFORMED	305.90	305.90
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	329.40	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	569.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	142.30	-
1	BOOTLID	DENTED	1,782.10	1,782.10
1	BOOTLID LOCK	DAMAGED	186.70	186.70
1	BOOTLID WEATHERSTRIPE	NOT NECESSARY	175.90	-
1	HYUNDAI LOGO	NECESSARY	59.60	59.60
1	ELANTRA WORDING	NECESSARY	62.80	62.80
	LESS 20% DISCOUNT		-864.98	-592.58
			3,459.92	2,370.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			390.00	230.00
<b><u>LABOUR</u></b>				
	TO PUTTY & SPRAY UP PAINT WORKS.		1,000.00	500.00
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	500.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO APPLY TUFF COAT.		150.00	40.00
	TO REMOVE UPHOLSTERY .		150.00	40.00

Report Ref No. CS/AGI23002042/Twy3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER BOOTLID FITTINGS.		150.00	80.00
			2,600.00	1,240.00
GRAND TOTAL			6,449.92	3,840.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/AGI23002042/Twy3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.