

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/HSB23002043/4973

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GSD11656

at Workshop m/s speedwork2

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Date / Time Action / Instruction

14/3/23 1/3 @ 12.000 inboard Kent (head @ 3422.37, 74%)

Date/Time, File Pass to?

1) 20/3 1/3 @ 12.000

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

Preli. Report

Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Veh No:

GSD11656

Yr Regn:

20/08/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM1

Make:

Toyota hiace

c.c

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

22443/

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P300142001

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5-

mm

R/Bal.

5-

mm

L/Bal.

5-

mm

L/Bal.

5-

mm

D.O.A.

21/02/23

D.O.I.

23/02/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 , #01-73 , AUTOBAY , SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Action
del
23/04/23
1/5 @ 12,000
10 days
Take place. After repair

VEHICLE NUMBER : GBD1165G
MAKE & MODEL: TOYOTA HIACE
DOA: 21/2/2023
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$1,217.00	20/seat
FRONT BONNET EMBLEM	1	\$73.50	1er
FRONT BONNET HINGE @83.60	2	\$167.50	11 X
FRONT BONNET LOCK	1	\$125.44	11 X
FRONT GRILLE	1	\$1,211.70	1er
FRONT GRILLE TOP COVER	1	\$64.12	X
FRONT FRILLE CENTRE GARNISH	1	\$286.00	X
FRONT SUPPORT PANEL	1	\$667.52	12 X
FRONT HEAD LAMP @1150	2	\$2,300.00	1/5 one 1pc
FRONT HEAD LAMP PANEL @215.50	2	\$431.00	11 X
FRONT BUMPER	1	\$1,295.00	2.1
FRONT BUMPER LOWER GRILLE	1	\$109.48	1er
FRONT BUMPER SIDE AIR GRILLE @77.00	2	\$154.00	1/5 one 1pc
FRONT BUMPER REINFORCEMENT BRACKET @112.00	2	\$224.00	1/5 one 1pc
FRONT BUMPER REINFORCEMENT	1	\$460.40	1er
FRONT BUMPER SIDE RETAINER @233.52	2	\$462.04	1/5 one 1pc
FRONT BUMPER TOP BEAM	1	\$213.22	12 X
FRONT AIR DUCT	1	\$223.58	11 X
AIR CLEANER BOX ASSY	1	\$1,081.78	11 X
AIR COND CONDENSER	1	\$1,675.66	1/5 one 1pc
RADIATOR	1	\$2,500.26	11 X
TURBO COOLER	1	\$1,245.00	11 X
TURBO COOLER COWLING	1	\$82.04	11 X
RADIATOR FAN COWLING (BIG)	1	\$385.28	11 X
RADIATOR FAN ASSY	1	\$1,911.28	11 X
AIRCOND DISCHARGE HOSE	1	\$276.00	11 X
AIRCOND LIQUID PIPE	1	\$215.30	11 X
RADIATOR SPARE TANK	1	\$371.28	11 X
RADIATOR TOP BRACKET @91.28	2	\$182.56	11 X
WIPER WASHER TANK	1	\$371.70	11 X
FRONT CORNER PANEL @252.90	2	\$505.80	11 X
FRONT WIPER GRILLE	1	\$679.70	11 X
BRAKE BOOSTER	1	\$1,859.30	11 X
BRAKE MASTER PUMP	1	\$906.08	11 X
REAR BOOT COVER	1	\$2,265.00	1/5 one 1pc
REAR BOOT RUBBER TOP GARNISH	1	\$82.70	1er
REAR BOOT RUBBER	1	\$328.50	1er
REAR BOOT LOCK	1	\$265.10	1/5 one 1pc
REAR BOOT HINGE @85.20	2	\$170.40	11 X
REAR BOOT ABSORBER @285.00	2	\$570.00	11 X
REAR BOOT CENTRE GARNISH	1	\$176.50	1er
REAR BOOT INNER BOARD	1	\$315.20	1er

REAR BOOT GLASS MOULDING		1	\$82.70	NS X
REAR WINDSCREEN GLASS	900.80	1	\$1,243.00	Shipped
REAR BOOT LOCK ACTUATOR	366.20	1	\$410.60	Assembled
REAR BOOT WIPER MOTOR		1	\$498.50	11X
REAR BOOT EMBLEM LOGO		1	\$65.20	new
REAR BOOT STICKER HIACE		1	\$38.50	NZ X
REAR END PANEL INNER		1	\$912.70	Body
REAR END PANEL OUTER		1	\$486.50	Body
REAR THIRD BRAKE LIGHT		1	\$410.40	11X
REAR FLOOR BOARD PANEL		1	\$2,381.40	R X
REAR BUMPER		1	\$498.00	D.S
REAR BUMPER SIDE RETAINER @60.80		2	\$121.60	Cnc
REAR BUMPER LOWER SUPPORT BRACKET @56.20		4	\$224.80	Buy
REAR NUMBER PLATE LAMP @65.60		2	\$131.20	11X
REAR TAILLAMP @352.30		2	\$704.60	Cnc/SNO
REAR TAILLAMP GARNISH @109.50	0/5 R	2	\$219.00	N/S TWI 1PC
TAILLAMP LOWER GARNISH RETAINER @49.20	0/5 R	2	\$98.40	N/S Cnc 1PC
REAR EXHAUST SILENCER		1	\$825.00	11X
REAR EXHAUST RUBBER @58.70		2	\$117.40	11X
REAR SPARE TYRE CARRIER		1	\$412.10	11X
REAR BOOT RUBBER TOP GARNISH		1	\$82.70	APPL X
TAILLAMP PANEL @282.70	0/5 R	2	\$565.40	N/S Buy 1PC
REAR SIDE PANEL @1813.60	1655.10 0/5 R	2	\$3,627.20	N/S BUC 1PC

\$42,269.82

Less 25 %

\$10,567.46

Sub Total

\$31,702.37

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT GRILLE CLIP	1	\$50.00	11X
FRONT NUMBER PLATE	1	\$45.00	But 20
REAR METAL FLOOR BOARD PANEL	1	\$1,600.00	NZ X
REAR BOOT INNER METAL PANEL	1	\$1,200.00	NZ X
REAR SIDE METAL PANEL @1850	2	\$3,700.00	NZ X
REAR BUMPER CLIP	1	\$50.00	new 30
REAR WINDSCREEN GLASS SEALANT	1	\$120.00	new 40
REAR 70KM STICKER	1	\$25.00	new 10
REVERSING SENSOR	1 set	\$450.00	200 S/W

Sub Total

\$7,240.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$100.00	30
APPLY ANTI RUST CHEMICAL		\$150.00	120
REMOVE AND REFIX REAR WINDSCREEN GLASS		\$150.00	120
REMOVE AND REFIX, RENEW REAR EXHAUST PIPE		\$150.00	11X
REMOVE AND REFIX REAR FLOOR MAT ETC		\$250.00	11X
REMOVE AND RENEW REVERSING SENSOR		\$150.00	50
LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE PORTION CUT, WELDING AND RENEW PART		\$3,500.00	1800
TO SPRAY PAINT AFFECTED PORTION		\$2,500.00	1400
REMOVE AND REFIX RADIATOR		\$80.00	11X
REMOVE AND REFIX RENEW AIRCON CONDENSER AND REFILL GAS		\$150.00	100

Sub Total

\$7,180.00

Grand Total \$46,122.37

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-14888.88
252

P-11151.73

S.N 300

L-3620

15071.73

208
12087