

Ats. P.C. BY:

REF:

CS/FCI 23002044/D94³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8THA 3206D Yr Regn: 2019/ May

CDE May 2027

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 533230 T/Radio: Insured / Std / NI / NA

Eng/No: 2ZR2C17487

C/No: JTDK.B3FU703080622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. 21/02/2023 D.O.I. 24/02/2023

Survey held at First Sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>First Capital SBS 3445G</u>
<u>06/06/23</u>	<u>frame L/S 12,300/- with 10 dgs 2/4</u>
	<u>(led \$ 1752.82, 58%)</u>

Date/Time, File Pass to?

06/06/23 First

Date/Time, File Return to?

2

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Other

Report Format: TP

1 senior, 2 junior, 1 P.P. to 1st

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 23-Feb-23

INSURANCE: First Capital

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 3206 D

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>Denhl</i>	1	\$1,303.29	\$1,303.29
REAR TRUNK LID LOCK <i>St/Den</i>	1	\$530.79	\$530.79
REAR TRUNK LID LOCK COVER <i>Sc</i>	1	\$ 129.80	\$ 129.80
REAR TRUNK LID LOCK SWITCH <i>Hu</i>	1	\$ 468.90	\$ 468.90
REAR TRUNK LID COVER TRIM BOARD <i>money broken</i>	1	\$254.40	\$254.40
Boot Lid Trimboard, Centre <i>Hu</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>Hu</i>	2	\$92.50	\$ 185.00
Boot Lid Trimboard REAR <i>Hu</i>	1	\$124.80	\$ 124.80
BOOT HANDLE <i>Sc</i>	1	\$31.80	\$31.80
REAR TRUNK LID RUBBER <i>deformed</i>	1	\$365.20	\$365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>shattered</i>	1	\$969.70	\$969.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>	1	\$1,054.71	\$1,054.71
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (HYBRID) <i>Hec</i>	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$81.43	\$81.43
THIRD BRAKE LIGHT <i>broken</i>	1	\$394.70	\$394.70
REAR TRUNK LID STRIKER <i>fy</i>	1	\$98.70	\$98.70
REAR TRUNK LID HINGE (LH/RH) <i>St</i>	2	\$189.50	\$379.00
REAR TRUNK LID ABSORBER (LH/RH) <i>Sc</i>	2	\$287.50	\$575.00
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>Sc</i>	2	\$127.90	\$255.80
REAR TRUNK LID STOPPER (LH/RH) <i>Hu</i>	2	\$84.80	\$169.60
SPOILERSUB-ASSY, REAR <i>broken</i>	1	\$1,787.79	\$1,787.79
REAR WINDSCREEN GLASS W/ MOULDING <i>Shattered</i>	1	\$1,884.32	\$1,884.32
ROOF TOP CENTER COVER - BLACK <i>dislodged</i>	1	\$956.30	\$956.30
ROOF TOP GARNISH SUB, LH <i>dislodged</i>	1	\$136.80	\$136.80
ROOF TOP GARNISH SUB, RH <i>dislodged</i>	1	\$136.80	\$136.80

✓
✓
X
X
✓
X
X
X
✓
✓
✓
✓
✓
✓
✓
X
✓
X
X
✓
✓
✓
✓

753.52

953.70

1758.70

REAR NO. PLATE LAMP LH/RH HH	2	\$163.50	\$327.00	X
MOTOR ASSY, REAR WIPER HH	1	\$734.60	\$734.60	X
ARM ASSY, REAR WIPER HH	1	\$84.70	\$84.70	X
BLADE ASSY, REAR WIPER HH	1	\$55.00	\$55.00	X
REAR BUMPER Dented	1	\$503.04	\$503.04	✓
REAR BUMPER RE-INFORCEMENT Dented	1	\$378.32	\$378.32	✓
REAR BUMPER LOWER COVER Dented	1	\$654.96	\$654.96	✓
REAR BUMPER SIDE RETAINER o/s broken 4/3 HH	2	\$112.70	\$225.40	✓
REAR BUMPER TOWING COVER detached SRC	1	\$82.70	\$82.70	broken X
REAR BUMPER CLIPS HH	1	\$22.00	\$22.00	✓
REAR BUMPER SIDE CLIP HH	2	\$25.00	\$50.00	X
REAR BUMPER UPPER STOPPER (LH/RH) HH	2	\$76.40	\$152.80	X
SEAL, REAR BUMPER SIDE, LH/RH o/s cut 4/3 HH	2	\$148.40	\$296.80	✓
REAR BUMPER UNDER SIDE COVER (LH/RH) mounting broken	2	\$232.00	\$464.00	✓
ARM SUB-ASSY, REAR BUMPER, (LH/RH) HH	2	\$139.60	\$279.20	X
REAR BUMPER REVERSE SENSOR Dented	1	\$235.70	\$235.70	✓
TAIL LAMP ASSY (UPPER) o/s broken 4/3 HH	2	\$557.90	\$1,115.80	✓
TAIL LAMP ASSY (LOWER) o/s broken 4/3 HH	2	\$570.00	\$1,140.00	✓
TAIL LAMP QUARTER PANEL o/s Dented 4/3 HH	2	\$216.00	\$432.00	✓
TAIL LAMP SIDE COVER o/s damaged 4/3 HH	2	\$256.00	\$512.00	✓
REAR TAILLAMP GUIDE - WHITE HH	1	\$95.30	\$95.30	X
REAR END PANEL Dented	1	\$738.96	\$738.96	✓
REAR END PANEL GARNISH deformed	1	\$294.80	\$294.80	✓
REAR SPARE TYRE PANEL leg	1	\$960.80	\$960.80	X
REAR END PANEL GARNISH COVER HH	1	\$138.90	\$138.90	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) ST	1	\$668.90	\$668.90	✓
REAR FIBER TOOL BOX TRIM (LH/RH) o/s broken 4/3 HH	2	\$598.00	\$1,196.00	✓
REAR FIBER TOOL BOX CENTER HH	1	\$186.20	\$186.20	X
REAR EXHAUST PIPE RH HH	1	\$1,163.40	\$1,163.40	X
REAR EXHAUST PIPE HANGER HH	1	\$40.70	\$40.70	X
REAR EXHAUST PIPE INSULATOR HH	1	\$314.60	\$314.60	X
REAR FENDER, RH Dented	1	\$992.04	\$992.04	✓
REAR FENDER INNER PANEL (RH) HH	1	\$728.00	\$728.00	X
REAR FENDER SHIELD (RH) HH	1	\$174.20	\$174.20	X
REAR FENDER TRIMBOARD (RH) crumpled	1	\$725.00	\$725.00	✓
REAR FENDER TOP COVER (BLACK COLOR)(RH) HH	1	\$301.10	\$301.10	X
REAR FENDER AIR DUCT deformed	1	\$165.10	\$165.10	✓

SUB TOTAL					\$29,188.53
LESS 20% $\div 5\%$					\$5,837.71
DISCOUNTED TOTAL					\$23,350.82
REVERSE CAMERA ASSY HH SN	1	\$380.00	\$380.00	X	
REAR TRUNK LOWER W/S MOULDING Hec HH SN	1	\$180.00	\$180.00	X	
REAR LOWER W/S SEALANT Hec SN	1	\$46.00	\$46.00	✓	
REAR WINDSCREEN SEALANT Hec SN	1	\$46.00	\$46.00	✓	
REAR NO. PLATE WITH COVER HH SN	1	\$100.00	\$100.00	X	
REAR TRUNK LID APPS STICKER Hec SN	1	\$40.00	\$40.00	✓	
REAR TRUNK LID COMFORT & TEL NO. STICKER Hec SN	1	\$60.00	\$60.00	✓	
REAR BUMPER RUBBER MAT Hec / damaged SN	1	\$50.00	\$50.00	✓	
SUB TOTAL					\$902.00
Labour Charge					
Panel Beating	1	\$2,200.00	\$2,200.00	1000/-	
Spray Painting Charge	1	\$1,800.00	\$1,800.00	900/-	
Wiring Charge	1	\$100.00	\$100.00	30/-	
Tuff Kote	1	\$100.00	\$100.00	40/-	
Towing Charge	1	\$80.00	\$80.00	HH	
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-	
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00	120/-	
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	HH	
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	HH	
TOTAL LABOUR					\$5,300.00
ESTIMATE TOTAL					\$29,552.82

17,400.43
13,050.32
=

242.00/-

1000/-
900/-
30/-
40/-
HH
80/-
120/-
HH
HH

2170.00/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com

24/02/2023 @ 1700hr

NA Auto

21km 10 deg.

1 year

24k Aut

15,462.32
1/5 12,300/-

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHA3206D

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Feb 2023

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Blue

Manufacturing Year:

2018

Engine No.:

2ZR2C17487

Chassis No.:

JTDKB3FU703080622

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

15 May 2019

First Registration Date:

15 May 2019

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 May 2027

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

14 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$22,309.00

COE Rebate Amount:

\$11,724.00

Total Rebate Amount:

\$22,409.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Feb 2023

OK