

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SLJ 6569S

Made : Volkswagen

Model : Jetta GP 1.4 TSI

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bootlid	1	\$ 1,903.15	\$ X nn 1,903.15
2	Rear Bootlid Lock	1	\$ 159.35	\$ X nn 159.35
3	Rear Bootlid Lock Striker	1	\$ 55.05	\$ X nn 55.05
4	Rear Bootlid Taillamp Reflector RH	1	\$ 255.85	\$ X nn 255.85
5	Rear Bootlid Taillamp Reflector LH	1	\$ 255.85	\$ X nn 255.85
6	Rear Bootlid Emblem	1	\$ 115.75	\$ X nn 115.75
7	Rear Bootlid Weatherstrip	1	\$ 323.85	\$ X nn 323.85
8	Rear Bootlid Hinge RH	1	\$ 126.85	\$ X nn 126.85
9	Rear Bootlid Hinge LH	1	\$ 126.85	\$ X nn 126.85
10	Rear Bootlid Inner Trim	1	\$ 220.75	\$ X nn 220.75
11	Rear Bumper	1	\$ 1,279.05	\$ fu ✓ 1,279.05
12	Rear Bumper Side Retainer RH	1	\$ 110.50	\$ X nn 110.50
13	Rear Bumper Side Retainer LH	1	\$ 110.50	\$ X nn 110.50
14	Rear Bumper Side Holder RH	1	\$ 115.50	\$ X nn 115.50
15	Rear Bumper Side Holder LH	1	\$ 115.50	\$ X nn 115.50
16	Rear Bumper Sponge	1	\$ 102.15	\$ X nn 102.15
17	Rear Bumper Reinforcement	1	\$ 696.45	\$ X nn 696.45
18	Rear Bumper Attachment Strip	1	\$ 84.95	\$ X nn 84.95
19	Rear Bumper Lower Garnish	1	\$ 656.75	\$ X nn 656.75
20	Rear Bumper Reflector RH	1	\$ 66.55	\$ X nn 66.55
21	Rear Bumper Reflector LH	1	\$ 66.55	\$ X nn 66.55
22	Rear Taillamp Assembly RH	1	\$ 377.85	\$ X nn 377.85
23	Rear Taillamp Assembly LH	1	\$ 377.85	\$ X nn 377.85
24	Rear Taillamp Lower Bracket RH	1	\$ 83.45	\$ X nn 83.45
25	Rear Taillamp Lower Bracket LH	1	\$ 83.45	\$ X nn 83.45
26	Rear Taillamp Panel RH	1	\$ 486.50	\$ X nn 486.50
27	Rear Taillamp Panel LH	1	\$ 486.50	\$ X nn 486.50
28	Rear End Panel	1	\$ 2,029.85	\$ nn X 2,029.85
29	Rear End Panel Top Garnish	1	\$ 145.75	\$ nn X 145.75
30	Rear Spare Tyre Panel Top Board	1	\$ 196.50	\$ nn X 196.50
31	Rear Fender RH	1	\$ 1,758.05	\$ bt-aga 1,758.05
32	Rear Fender Inner Trim RH	1	\$ 306.65	\$ X nn 306.65

✓

✓

33	Rear Fender Inner Cowling RH	1	\$	302.15	\$	X nn	302.15	
34	Rear Fender Air Vent RH	1	\$	65.15	\$	x nn	65.15	
35	Rear Wheel Rim RH	1	\$	1,073.59	\$	cut	1,073.59	✓
36	Rear Shock Absorber RH	1	\$	595.34	\$	x nn	595.34	
37	Rear Lower Arm RH	1	\$	380.20	\$	x nn	380.20	
38	Rear Upper Arm RH	1	\$	385.20	\$	X nn	385.20	
39	Rear Knuckle Arm RH	1	\$	659.75	\$	X ? nn	659.75	
40	Rear Wheel Hub with Bearing RH	1	\$	627.71	\$	X ? nn	627.71	
41	Rocker Panel RH	1	\$	1,016.83	\$	bt	1,016.83	✓
42	Rear Door RH	1	\$	1,719.03	\$	bt	1,719.03	✓
43	Rear Door Upper Hinge RH	1	\$	101.56	\$	x nn	101.56	
44	Rear Door Lower Hinge RH	1	\$	101.56	\$	X ? nn	101.56	
45	Rear Door Glass Outer Moulding RH	1	\$	98.06	\$	x nn	98.06	
46	Rear Door Lock RH	1	\$	369.55	\$	x nn	369.55	
47	Rear Door Weatherstrip RH	1	\$	129.35	\$	cut	129.35	✓
48	Rear Door Inner Trim Board RH	1	\$	1,038.95	\$	X ? nn	1,038.95	
49	Rear Door Window Glass Regulator RH	1	\$	386.05	\$	X ? nn	386.05	
50	Front Door RH	1	\$	1,963.45	\$	bt	1,963.45	✓
51	Front Door Upper Hinge RH	1	\$	107.24	\$	x nn	107.24	
52	Front Door Lower Hinge RH	1	\$	107.24	\$	x nn	107.24	
53	Front Door Glass Outer Moulding RH	1	\$	98.06	\$	x nn	98.06	
54	Front Door Lock RH	1	\$	357.50	\$	X ? nn	357.50	
55	Front Door Weatherstrip RH	1	\$	114.30	\$	ner	114.30	✓
56	Front Door Inner Trim Board RH	1	\$	1,214.55	\$	X ? nn	1,214.55	
57	Front Door Window Glass Regulator RH	1	\$	507.48	\$	X ? nn	507.48	
58	Front Door Outer Handle RH	1	\$	485.17	\$	cut	485.17	✓
59	Front Door Side Mirror Assembly RH	1	\$	704.97	\$	bt x nn	704.97	
60	Front Door Side Mirror Cover RH	1	\$	186.39	\$	Ry	186.39	
61	Front Door Side Mirror Glass RH	1	\$	211.93	\$	x nn	211.93	
62	Front Fender RH	1	\$	654.51	\$	Ry	654.51	
63	Front Fender Bracket RH	1	\$	54.96	\$	x nn	54.96	
64	Front Fender Inner Cowling RH	1	\$	205.69	\$	x nn	205.69	
65	Front Wheel Rim RH	1	\$	1,073.59	\$	x nn	1,073.59	
66	Front Wheel Bearing With Mounting RH	1	\$	618.43	\$	x nn	618.43	
67	Front Wheel Bearing Housing RH	1	\$	667.71	\$	x nn	667.71	
68	Bonded Rubber Mounting RH	1	\$	26.82	\$	A nn	26.82	
69	Front Lower Arm RH	1	\$	383.60	\$	x nn	383.60	
70	Front Lower Arm Ball Joint RH	1	\$	130.60	\$	x nn	130.60	
71	Front Shock Absorber RH	1	\$	542.10	\$	x nn	542.10	
72	Suspension Strut Mounting RH	1	\$	139.72	\$	A nn	139.72	
73	Tie Rod RH	1	\$	115.19	\$	x nn	115.19	
74	Tie Rod End RH	1	\$	147.14	\$	x nn	147.14	
75	Front Drive Shaft RH	1	\$	2,573.10	\$	x nn	2,573.10	
76	Steering Rack and Pinion	1	\$	3,878.90	\$	x nn	3,878.90	
77	Front Headlamp Assembly RH	1	\$	779.89	\$	x nn	779.89	

78	Front Bumper	1	\$	1,510.28	\$ AX nn 1,510.28
79	Front Bumper Lower Spoiler	1	\$	521.23	\$ X nn 521.23
80	Front Bumper Side Retainer RH	1	\$	41.09	\$ X nn 41.09
81	Front Bumper Side Retainer LH	1	\$	41.09	\$ X nn 41.09
82	Front Bumper Centre Bracket	1	\$	119.02	\$ X nn 119.02
83	Front Radiator Grille	1	\$	526.05	\$ X nn 526.05
84	Front Bumper Centre Lower Grille	1	\$	238.04	\$ X nn 238.04
85	Front Bumper Fog Lamp Grille RH	1	\$	127.04	\$ X nn 127.04
86	Front Bumper Fog Lamp Grille Lower Trim RH	1	\$	73.09	\$ X nn 73.09
87	Front Bumper Fog Lamp RH	1	\$	301.56	\$ X nn 301.56
88	Front Support Panel	1	\$	1,219.56	\$ X nn 1,219.56
89	Horn	1	\$	123.89	\$ X nn 123.89
90	Wiper Washer Tank	1	\$	128.79	\$ X nn 128.79
			Parts Sub Total :		\$ 45,351.14
			10% Discount		\$ 4,535.11
			PARTS TOTAL :		\$ 40,816.03

9538.82
-10%
8594.93

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ X nn 50.00
2	Front Number Plate	1	\$ 50.00	\$ X nn 50.00
3	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30 net ✓ 50.00
4	Rear Bootlid Inner Trim Clips - Set	1	\$ 50.00	\$ X nn 50.00
5	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ X nn 50.00
6	Rear Fender Inner RH Trim Clips - Set	1	\$ 50.00	\$ X nn 50.00
7	Rear Fender Inner Cowling RH Clips - Set	1	\$ 50.00	\$ X nn 50.00
8	Rear Door Inner Trim Board RH Clips - Set	1	\$ 50.00	\$ X nn 50.00
9	Front Door Inner Trim Board RH Clips - Set	1	\$ 50.00	\$ X nn 50.00
10	Front Fender Inner Cowling RH Clips - Set	1	\$ 50.00	\$ X nn 50.00
11	Front Bumper Clips - Set	1	\$ 50.00	\$ 30 net ✓ 50.00
12	Front Radiator Grille Clips - Set	1	\$ 50.00	\$ X nn 50.00
13	Rear Bootlid Sealant	1	\$ 150.00	\$ X nn 150.00
14	Rear End Panel Sealant	1	\$ 150.00	\$ X nn 150.00
15	Rear Fender RH Sealant	1	\$ 150.00	\$ X - 50 ✓ 150.00
16	Rear Door RH Sealant	1	\$ 150.00	\$ X nn 150.00
17	Front Door RH Sealant	1	\$ 150.00	\$ X nn 150.00
18	Front Fender RH Sealant	1	\$ 150.00	\$ X nn 150.00
19	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ X nn 150.00
20	Rear Tyre RH	1	\$ 500.00	\$ X nn 500.00
21	Front Tyre RH	1	\$ 500.00	\$ X nn 500.00
22	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ X nn 250.00
23	Rear Bootlid Reverse Camera	1	\$ 550.00	\$ X nn 550.00
		110	SPECIAL NETT TOTAL :	\$ 3,450.00

110

Nos.	LABOUR		TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	800	\$ 2,400.00
2	To Spray Paint Affected Areas	1000	\$ 2,000.00
3	Wiring & Bulb Check		\$ X 100.00
4	To Transfer Rear Bootlid Mechanism		\$ X 150.00
5	To Transfer Rear Door Mechanism RH		\$ 60 150.00
6	To Transfer Front Door Mechanism RH		\$ 60 150.00
7	To Remove & Refix Rear Windscreen Glass		\$ 120 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor		\$ 30 120.00
9	To Remove & Refix Rear Bootlid Reverse Camera		\$ X 150.00
10	To Remove & Refix Rear Exhaust Pipe		\$ X 150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs		\$ 60 150.00
12	To Remove & Refix Fuel Tank to facilitate repairs		\$ X 200.00
13	To Remove & Refix Aircon Condenser and Top Up Gas		\$ X 150.00
14	To Remove & Refix Radiator and Pressure Test		\$ X 150.00
15	To Remove & Refix Rear Undercarriage		\$ 150? X 500.00
16	To Remove & Refix Front Undercarriage		\$ X 500.00
17	To Remove & Refix Both Front and Rear Tyres and Conduct Wheel Balancing		\$ X 150.00
18	To Conduct Four Wheel Alignment		\$ 80 150.00
19	To apply anti rust on affected parts		\$ 40 100.00
20	To Conduct Water Leak Test		\$ X 100.00
21	To Send for Diagnostic and Reset Control Unit. Programming & Calibration		\$ X 480.00
2250		LABOUR TOTAL :	\$ 8,150.00

Tanfkin at 7249549
 w/p 27/2/23 @ 245
 L/S Resurvey after repair
 Tanfkin @ Khairat
 7 days
 - To check consistency of accident
 - To check part prices

PARTS TOTAL : \$ 40,816.03
 SPECIAL NETT TOTAL : \$ 3,450.00
 LABOUR TOTAL : \$ 8,150.00
GRAND TOTAL : \$ 52,416.03

10,954.93

L/S - 8763.94
 = 8750

L&K Auto Consultant's hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: