į.	=
S. RECEY TOUTHE - CS/C1/2	7 2 1
	3002095 7003
ASSI	GNMENT
From: Date:	Veh No: SLJ6569S YT Regn: 2016 Dec.
Estimated lost	Type: MCEP/M.Cyple / Pus / Van / Lony / Taxi / Prime Mover /
OD (I VS) TO RES / OD RES / EVA / INV / MV	Trusk / Traller or
To Inspective No:	Maka: Vollisiony Jeta . C.C 1310
च Worksराष्ट्र गरम	Colour Gray A/C: Insured / Std / NO / NA
ৰ্য	The state of the
nsued:	Sp.Reading 94 061 T/Radio: insured / Std / NT / NA
Policy No.	
Claims Ni.	C/No: WUNZZZZ 16ZGMOZ/ZY3.
Sum insuled: Excess:	Gett. Cond: Good / Fair / Poor / Burnt
(Client'sRecol)	Steering: inordia / Jammed / Leaked / Burnt or Brake: India / Jammed / Leaked / Burnt or
Vialke of Valu	And I married I married Of
8	Modi: Nii / Dim / STD A/Rim or
(Piblicy Condition)	Tyre Size: P. 223/45M7
Remand The ven had commenced the N/S O/S ?	RE COUNTY EVALUATE A COURT OF THE COURT OF T
repaired the time of inspection.	BS / DUN / EXNOVA / BY I FB I LIZA (MIC) DHTSU / PIR / SUMI /
Ball, or Warket Value: 455 K.	Front
DAC Acsident Root: Consistent? : Yes or No	R/Bal. C mm R/Bal. C mm
SIA / PR Septi Consistent? : Yes or No Est. Repairs: days Res.: Yes or No	MBal. 6 mm . MBal 6- mm
	D.O.A. D.O.I. 27/2/23
1: M	Survey held at Bifust.
JA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / 0/8 / NJS / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The III of the
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	1
sta/lime, File Pass 407 : Pre!i. Report	
- Final Second	Days Of Repair:
mis/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fee	Transportation:
	100000000000000000000000000000000000000
opens Corpust : http://district.ide.com/	Term, consett of the second
and a serie (separate a b	

Bifrost Auto Pte Ltd

8 Kakı Bukit Ave 4 #01-49, Premier @ Kakı Bukit Singabore 415875 Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE:	Vehicle Nos :	SLJ 6569S
Date of Survey :	Made :	Volkswagen
Date of ReSurvey:	Model:	Jetta GP 1.4 TSI
Contacts :	Chassis No :	
* AGREED Cost Of Repair and Repair Day/s with SJE *	- CONTRACTO	
Amount:	Working Day:	

Nos.	PARTS	Qty	Unit S\$	TOTAL	. S\$
1	Rear Bootlid	1	\$ 1,903.15	\$ ×	1,903.15
2	Rear Bootlid Lock	1	\$ 159.35	\$ X	159.35
3	Rear Bootlid Lock Striker	1	\$ 55.05	\$ X	55.05
4	Rear Bootlid Taillamp Reflector RH	1	\$ 255.85	\$ X	255.85
5	Rear Bootlid Taillamp Reflector LH	1	\$ 255.85	\$ X	255.85
6	Rear Bootlid Emblem	1	\$ 115.75	\$ X	115.75
7	Rear Bootlid Weatherstrip	1	\$ 323.85	\$ X	323.85
8	Rear Bootlid Hinge RH	1	\$ 126.85	\$ X	126.85
9	Rear Bootlid Hinge LH	1	\$ 126.85	\$ X	126.85
10	Rear Bootlid Inner Trim	1	\$ 220.75	\$ ×	220.75
11	Rear Bumper	1	\$ 1,279.05	\$ tu-	1,279.05
12	Rear Bumper Side Retainer RH	1	\$ 110.50	\$ X	110.50
13	Rear Bumper Side Retainer LH	1	\$ 110.50	\$ X	110.50
14	Rear Bumper Side Holder RH	1	\$ 115.50	\$ <	115.50
15	Rear Bumper Side Holder LH	1	\$ 115.50	\$ X	115.50
16	Rear Bumper Sponge	1	\$ 102.15	\$ X	102.15
17	Rear Bumper Reinforcement	1	\$ 696.45	\$ ×	696.45
18	Rear Bumper Attachment Strip	1	\$ 84.95	\$ X	84.95
19	Rear Bumper Lower Garnish	1	\$ 656.75	\$ ×	656.75
20	Rear Bumper Reflector RH	1	\$ 66.55	\$ X	66.55
21	Rear Bumper Reflector LH	1	\$ 66.55	\$ Χ	66.55
22	Rear Taillamp Assembly RH	1	\$ 377.85	\$ X	377.85
23	Rear Taillamp Assembly LH	1	\$ 377.85	\$ X	377.85
24	Rear Taillamp Lower Bracket RH	1	\$ 83.45	\$ X	83.45
25	Rear Taillamp Lower Bracket LH	1	\$ 83.45	\$ ×	83.45
26	Rear Taillamp Panel RH	1	\$ 486.50	\$ A	486.50
27	Rear Taillamp Panel LH	1	\$ 486.50	\$ ×	486.50
28	Rear End Panel	1	\$ 2,029.85	\$ X	2,029.85
29	Rear End Panel Top Garnish	1	\$ 145.75	\$ ×	145.75
30	Rear Spare Tyre Panel Top Board	1	\$ 196.50	\$ ×	196.50
31	Rear Fender RH	1	\$ 1,758.05	\$ H- RA	1,758.09
32	Rear Fender Inner Trim RH	1	\$ 306.65	\$ X	306.69

33	Rear Fender Inner Cowling RH	1	\$ 302.15	\$ X	302.15
34	Rear Fender Air Vent RH	1	\$ 65.15	\$ X	65.15
35	Rear Wheel Rim RH	1	\$ 1,073.59	\$ ent-	1,073.59
36	Rear Shock Absorber RH	1	\$ 595.34	\$ ×	595.34
37	Rear Lower Arm RH	1	\$ 380.20	\$ X	380.20
38	Rear Upper Arm RH	1	\$ 385.20	\$ *	385.20
39	Rear Knuckle Arm RH	1	\$ 659.75	\$ Ś	659.75
40	Rear Wheel Hub with Bearing RH	1	\$ 627.71	\$?	627.71
41	Rocker Panel RH	1	\$ 1,016.83	\$ 27-	1,016.83
42	Rear Door RH	1	\$ 1,719.03	\$ 69-	1,719.03
43	Rear Door Upper Hinge RH	1	\$ 101.56	\$ ×	101.56
44	Rear Door Lower Hinge RH	1	\$ 101.56	\$ 3	101.56
45	Rear Door Glass Outer Moulding RH	1	\$ 98.06	\$ ×	98.06
46	Rear Door Lock RH	1	\$ 369.55	\$ ×	369.55
47	Rear Door Weatherstrip RH	1	\$ 129.35	\$ wh	129.35
48	Rear Door Inner Trim Board RH	1	\$ 1,038.95	\$ 7	1,038.95
49	Rear Door Window Glass Regulator RH	1	\$ 386.05	\$ 3	386.05
50	Front Door RH	1	\$ 1,963.45	\$ bt-	1,963.45
51	Front Door Upper Hinge RH	1	\$ 107.24	\$ ×	107.24
52	Front Door Lower Hinge RH	1	\$ 107.24	\$ ×	107.24
53	Front Door Glass Outer Moulding RH	1	\$ 98.06	\$ *	98.06
54	Front Door Lock RH	1	\$ 357.50	\$ 7	357.50
55	Front Door Weatherstrip RH	1	\$ 114.30	\$ ner	114.30
56	Front Door Inner Trim Board RH	1	\$ 1,214.55	\$ 2	1,214.55
57	Front Door Window Glass Regulator RH	1	\$ 507.48	\$ 7.	507.48
58	Front Door Outer Handle RH	1	\$ 485.17	\$ cut	485.17
59	Front Door Side Mirror Assembly RH	1	\$ 704.97	\$ de X	704.97
60	Front Door Side Mirror Cover RH	1	\$ 186.39	\$ Ry	186.39
61	Front Door Side Mirror Glass RH	1	\$ 211.93	\$ DK.	211.93
62	Front Fender RH	1	\$ 654.51	\$ Ry	654.51
63	Front Fender Bracket RH	1	\$ 54.96	\$ ×	54.96
64	Front Fender Inner Cowling RH	1	\$ 205.69	\$ X	205.69
65	Front Wheel Rim RH	1	\$ 1,073.59	\$ ×	1,073.59
66	Front Wheel Bearing With Mounting RH	1	\$ 618.43	\$ ×	618.43
67	Front Wheel Bearing Housing RH	1	\$ 667.71	\$ ×	667.71
68	Bonded Rubber Mounting RH	1	\$ 26.82	\$ Χ	26.82
69	Front Lower Arm RH	1	\$ 383.60	\$ X	383.60
70	Front Lower Arm Ball Joint RH	1	\$ 130.60	\$ X	130.60
71	Front Shock Absorber RH	1	\$ 542.10	\$ ×	542.10
72	Suspension Strut Mounting RH	1	\$ 139.72	\$ X	139.72
73	Tie Rod RH	1	\$ 115.19	\$ ×	115.19
74	Tie Rod End RH	1	\$ 147.14	\$ X	147.14
75	Front Drive Shaft RH	1	\$ 2,573.10	\$ ×	2,573.10
76	Steering Rack and Pinion	1	\$ 3,878.90	\$ ×	3,878.90
77	Front Headlamp Assembly RH	1	\$ 779.89	\$ ×	779.89

78	Front Bumper	1	\$ 1,510.28	\$ AX	1,510.28
79	Front Bumper Lower Spoiler	1	\$ 521.23	\$ X	521.23
80	Front Bumper Side Retainer RH	1	\$ 41.09	\$ X	41.09
81	Front Bumper Side Retainer LH	1	\$ 41.09	\$ X	41.09
82	Front Bumper Centre Bracket	1	\$ 119.02	\$ De	119.02
83	Front Radiator Grille	1	\$ 526.05	\$ K	526.05
84	Front Bumper Centre Lower Grille	1	\$ 238.04	\$ K	238.04
85	Front Bumper Fog Lamp Grille RH	1	\$ 127.04	\$ Х	127.04
86	Front Bumper Fog Lamp Grille Lower Trim RH	1	\$ 73.09	\$ K	73.09
87	Front Bumper Fog Lamp RH	1	\$ 301.56	\$ k	301.56
88	Front Support Panel	1	\$ 1,219.56	\$ ٢	1,219.56
89	Horn	1	\$ 123.89	\$ ×	123.89
90	Wiper Washer Tank	1	\$ 128.79	\$ X	128.79
			Parts Sub Total :	\$	45,351.14
		10%	Discount	\$	4,535.11
			PARTS TOTAL:	\$	40,816.03

Nos.	SPECIAL NETT		Qty		Unit S\$	TOTAL S	\$
1	Rear Number Plate		1	\$	50.00	\$ ×	50.00
2	Front Number Plate		1	\$	50.00	\$ У	50.00
3	Rear Bumper Clips - Set		1	\$	50.00	\$ 30 mg-	50.00
4	Rear Bootlid Inner Trim Clips	- Set	1	\$	50.00	\$ ×	50,00
5	Rear End Panel Top Garnish (Clips - Set	1	\$	50.00	\$ X	50.00
6	Rear Fender Inner RH Trim Cl	ips - Set	1	\$	50.00	\$ K	50.00
7	Rear Fender Inner Cowling RI	H Clips - Set	1	\$	50.00	\$ K	50.00
8	Rear Door Inner Trim Board F	RH Clips - Set	1	\$	50.00	\$ ×	50.00
9	Front Door Inner Trim Board	RH Clips - Set	1	\$	50.00	\$ X,	50.00
10	Front Fender Inner Cowling R	H Clips - Set	1	\$	50.00	\$ ×	50.00
11	Front Bumper Clips - Set		1	\$	50.00	\$ 30ml-	50.00
12	Front Radiator Grille Clips - S	et	1	\$	50.00	\$ X	50.00
13	Rear Bootlid Sealant		1	\$	150.00	\$ X	150.00
14	Rear End Panel Sealant		1	\$	150.00	\$ ×	150.00
15	Rear Fender RH Sealant		1	\$	150.00	\$ K4-50	150.00
16	Rear Door RH Sealant		1	\$	150.00	\$ X	150.00
17	Front Door RH Sealant		1	\$	150.00	\$ X	150.00
18	Front Fender RH Sealant		1	\$	150.00	\$ X	150.00
19	Rear Windscreen Glass Seala	nt	1	\$	150.00	\$ ×	150.00
20	Rear Tyre RH		1	\$	500.00	\$ Х	500.00
21	Front Tyre RH		1	\$	500.00	\$ ×	500.00
22	Rear Bumper Reverse Sensor	- Set	1	\$	250.00	\$ X	250.00
23	Rear Bootlid Reverse Camera	i I	1	\$	550.00	\$ K	550.00
			SPI	CIAL	NETT TOTAL :	\$ 3	,450.00

Nos.	LABOUR	TOTAL	. S\$
1	To Panel Beat, Remove & Refix Parts	\$	2,400.00
2	To Spray Paint Affected Areas /000	\$	2,000.00
3	Wiring & Bulb Check	\$ ×	100.00
4	To Transfer Rear Bootlid Mechanism	\$ ×	150.00
5	To Transfer Rear Door Mechanism RH	\$ 60	150.00
6	To Transfer Front Door Mechanism RH	\$ 60	150.00
7	To Remove & Refix Rear Windscreen Glass	\$ 120	150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30	120.00
9	To Remove & Refix Rear Bootlid Reverse Camera	\$ Ŋ	150.00
10	To Remove & Refix Rear Exhaust Pipe	\$ X	150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60	150.00
12	To Remove & Refix Fuel Tank to facilitate repairs	\$ ×	200.00
13	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X	150.00
14	To Remove & Refix Radiator and Pressure Test	\$ ×	150.00
15	To Remove & Refix Rear Undercarriage	\$ 150?	500.00
16	To Remove & Refix Front Undercarriage	\$ ×	500.00
17	To Remove & Refix Both Front and Rear Tyres and Conduct Wheel Balancing	\$ X	150.00
18	To Conduct Four Wheel Alignment	\$ 80	150.00
19	To apply anti rust on affected parts	\$ 40	100.00
20	To Conduct Water Leak Test	\$ X	100.00
21	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
	LABOUR TOTAL :	\$	8,150.00

Tauflin erf, 9249549 wp/ 27/2/23024

PARTS TOTAL: \$ 40,816.03

SPECIAL NETT TOTAL: \$ 3,450.00

LABOUR TOTAL : \$ 8,150.00

GRAND TOTAL : \$ 52,416.03

tenfthis clkhartiwn 7days

- To Much was stry afaccillat

LKK Auto Consultan's hence nouty

the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 30 Jan 2023

Singapore NRIC

5701

SLJ6569S

Yes

30 Jan 2023

VOLKSWAGEN

JETTA GP 1.4 TSI 90 A/T TL 1632G5

Silver 2015

2015

CAXF84071

WVWZZZ16ZGM021243

90.0 kW (120 bhp)

\$17,516.00

20 Dec 2016

20 Dec 2016

2

\$17,516.00

Yes

19 Dec 2026

\$11,385.00

19 Dec 2026

A - Car up to 1600cc & 97kW (130bhp)

10

\$48,000.00

\$18,645.00

\$30,030.00

ОК

Date of Accident	: 21/01/23 Accide	ent Time: _ 2021 (2	4-HR-FORMAT)
Accident Place	: I'B custom	bwards Joh	or Malaysia.
Vehicle Reg. No (Car plate No.)	91165698 CC: Vehi	cle Make/Model: Vo.	Kusuagen Setta
Insurance Company	117	Policy No. 5/2	
Name of Registered Owner	: Company / Individual	Osman Bin	Any
ID of Registered Owner	: Co Reg No:	Owner's NRIC N	o: 81255520T
OWNER EMAIL ADDRESS:			A STATE OF THE PARTY OF THE PAR
osmanary 28 @ guard. com	- ' .	Owner's Contact	No: 7,33 /37/
DRIVER'S Name	: 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	DRIVER'S NRIC No	
DRIVER'S Date of Birth	: 28/10/57 DRIVE	R'S License Pass Date	16/04/ 78
Relationship bet. Owner & Driver	: Spouse \ Parents \Children		1 70 . 10
DRIVER'S Address	: bleck 253A AM	K St 21 AC	6-171 8 (561253)
DRIVER'S Contact No./ Alt No.	: 1)	2)	
DRIVER'S Occupation	: INDOOR (OUTDOOR (e	g. working inside or ou	tside of an ofc)
Email Address	:		
Weather & Road Surface	: CLEAR & DRY \ RAINI	G & WET \AFTER R	AIN & WET
Reporting Type	: Reporting Only \ Claim C	ther Party \ Claim Ow	n Insurance
Number of Passengers (including Dr Was the accident reported to the poli Was there any video Captured by car Exact purpose for which vehicle was Any injuries, if yes(name of the in	camera: YES \ NO)		
	Party Driver's Particulars	- 0	
Vehicle Reg No: 9LN 3799	T Vehicle Reg N	11.6.	NA NA
Vehicle Make\Model:	Vehicle Make\	Model:	
Name DRIVER:		k:	
IC No. DRIVER:	IC No. DRIVE	R:	
DRIVER'S Contact & add:		ntact & add:	
REPORT FORM EXPLAINED IN : ENGLISH		ERS:	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my daims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

& Time

Wilnessed by Reporting Centre Personnel (Name as in NRIC/ID card)



scribe Circumstance of the Accident					
1 in travelling Pore	and ala	110	1B 16	ndomo	bank
I was travelling Stran	grii au	9		,,	7000100
John Malongeia. / was	Plationa	ms a	lue of	6 He	traffir
gord , restriction , soul	67-17.17	1			7.0,
am. Out of Sudelen,	1 felt	an	impac	+ Fr	on my
					- 1
threle right side port	ion. When	1 5	not d	0421,	/ real no
430		1.050			
that vehicle (m) has	collided	01100	nie	While	re
	1.				
pas bying to fwitch	IGhe.		was the same		
			1000-00		
					2780110
			-		
	-				
	7/14				
Declaration I/We declare the foregoing particulars are true in every res	nect		3.5		
Make decisive the tollegoing bandonals are true in every les	,				
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Mala	M				
Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyhold	er)/Date	Wilnessed b	y Reporting Co	entre Personnel